

AD-A154 496


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
WASHINGTON MOUNTAIN L... (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV DEC 79


1/2

UNCLASSIFIED

F/G 13/13

NL





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A154 496

HOUSATONIC RIVER BASIN  
WASHINGTON, MASSACHUSETTS

WASHINGTON MOUNTAIN LAKE DAM  
MA 00318

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

DTIC FILE COPY



DTIC  
ELECTE  
JUN 4 1985  
S D E

DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS. 02154

DECEMBER 1979

This document is not to be  
distributed outside the  
Department of the Army.

This document has been approved  
for public release and sale by  
distribution is unlimited.

85 5 20 096

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00318	2. GORT ACCESSION NO. A134496	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle)  Washington Mountain Lake Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE December 1979
		13. NUMBER OF PAGES 45
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		18a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY,  Housatonic River Basin Washington, Massachusetts Washington Mountain Brook (Tributary of the Housatonic River)		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  The dam is an earth embankment 1145 ft. long and 44 ft. high at the downstream toe with a drop inlet service spillway structure and a 30 inch outlet conduit. The size of the dam is intermediate and the hazard potential is high. The dam was found to be in fair condition. The drainage area of the dam is 1.3 square miles and is made up primarily of rolling hill woodland.		



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
424 TRAPELO ROAD  
WALTHAM, MASSACHUSETTS 02154

REPLY TO  
ATTENTION OF  
NEDED

AUG 06 1980

Honorable Edward J. King  
Governor of the Commonwealth of  
Massachusetts  
State House  
Boston, Massachusetts 02133

Dear Governor King:

Inclosed is a copy of the Washington Mountain Lake Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, Commonwealth of Massachusetts, Division of Forests & Parks, 100 Cambridge Street, Boston, Massachusetts 02202.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely,

*Max B. Scheider*

MAX B. SCHEIDER  
Colonel, Corps of Engineers  
Division Engineer

Incl  
As stated

WASHINGTON MOUNTAIN LAKE DAM  
MA 00318

HOUSATONIC RIVER BASIN  
WASHINGTON, MASSACHUSETTS

Accession For		
NTIS GRA&I <input checked="" type="checkbox"/>		
DTIC TAB <input type="checkbox"/>		
Unannounced <input type="checkbox"/>		
Justification		
By		
Distribution/		
Availability Codes		
Dist	Avail and/or Special	
A/		

PHASE I INSPECTION REPORT  
NATONAL DAM INSPECTION PROGRAM



NATIONAL DAM INSPECTION PROGRAM  
PHASE I REPORT

Identification No.: MA 00318  
Mass. DPW No.: 1-2-313-11  
Name of Dam: Washington Mountain Lake Dam  
Town: Washington  
County and State: Berkshire County, Massachusetts  
Stream: Washington Mountain Brook (Tributary  
of the Housatonic River)  
Date of Inspection: November 2, 1979

BRIEF ASSESSMENT

The Washington Mountain Lake Dam is located in the watershed of Washington Mountain Brook, a tributary of the Housatonic River, approximately 3 miles upstream of the confluence of Washington Mountain Brook with the Housatonic River in Lee, Massachusetts. [ The dam is an earth embankment 1145 feet long and 44 feet high at the downstream toe with a drop inlet service spillway structure and a 30-inch outlet conduit.] An emergency spillway 50 feet wide is cut into the right abutment. A dike consisting of an earth embankment impounds water to form the lake in conjunction with the dam. The dike is located approximately 3500 feet east of the dam. The dike is the subject of a separate report.

The dam is owned by the Commonwealth of Massachusetts, Division of Forests and Parks. It was designed by the Soil Conservation Service for the purpose of flood protection and recreation in the October Mountain State Forest.

The drainage area of the dam is 1.3 square miles and is made up primarily of rolling hill woodland. The dam impounds 3225 acre-feet at low stage but has a maximum impoundment of 4575 acre-feet at top of dam. The dam is INTERMEDIATE in size and its hazard classification is HIGH since significant property damage and loss of life could result in the event of a dam failure.


The dam has not impounded a normal pool of water to date due to the existence of an underground telephone cable in the pool area which is scheduled to be relocated in the near future. Some flood runoff is impounded periodically but eventually released through the pond drain sluice gate, which to date has been left open.

The test flood for this dam is the Probable Maximum Flood (PMF). The peak inflow for this flood is 3,000 cfs. Because of storage and the spillway capacity the runoff volume will be contained in the reservoir. The peak discharge will be about 600 cfs and the reservoir stage will be at elevation 1,803 feet (MSL).

The dam and appurtenances were found to be in FAIR condition. Remedial measures to be undertaken by the owner include: investigate source of silt and gravel in foundation drains, repair broken foundation drain pipe outlets, repair tire ruts on the top of the dam, fill emergency spillway at the top of the left slope to top of dam elevation,

repair concrete at the impact basin, repair the gate operator and base, prevent trespassing on slopes, clean debris from the downstream flow conduit, investigate the change in slope of the pond drain pipe, operate the drain gate as an annual inspection program and develop a formal written emergency flood warning system.

The remedial measures outlined above should be implemented within one year of receipt of this report by the owner. The program of annual technical inspections should be continued.



John W. Powers  
Massachusetts Registration 23106



This Phase I Inspection Report on Washington Mountain Lake Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

*Richard J. Di Bruno*

RICHARD DIBUONO, MEMBER  
Water Control Branch  
Engineering Division

*Aramast Mahtesian*

ARAMAST MAHTESIAN, MEMBER  
Geotechnical Engineering Branch  
Engineering Division

*Carney M. Terzian*

CARNEY M. TERZIAN, CHAIRMAN  
Design Branch  
Engineering Division

APPROVAL RECOMMENDED:

*Joe B. Fryar*

JOE B. FRYAR  
Chief, Engineering Division

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

## TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
LETTER OF TRANSMITTAL	
BRIEF ASSESSMENT	
REVIEW BOARD SIGNATURE SHEET	
PREFACE	i
TABLE OF CONTENTS	ii-iii
OVERVIEW PHOTO	iv
LOCUS PLAN 1	v
LOCUS PLAN 2	vi

## REPORT

1. PROJECT INFORMATION	
1.1 General	1-1
1.2 Description of Project	1-1
1.3 Pertinent Data	1-5
2. ENGINEERING DATA	
2.1 Design Data	2-1
2.2 Construction Data	2-1
2.3 Operational Data	2-1
2.4 Evaluation of Data	2-1
3. VISUAL INSPECTION	
3.1 Findings	3-1
3.2 Evaluation	3-2
4. OPERATIONAL AND MAINTENANCE PROCEDURES	
4.1 Operational Procedures	4-1
4.2 Maintenance Procedures	4-1
4.3 Evaluation	4-1
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	
5.1 General	5-1
5.2 Design Data	5-1
5.3 Experience Data	5-1
5.4 Visual Observations	5-1
5.5 Test Flood Analysis	5-2
5.6 Dam Failure Analysis	5-3

<u>Section</u>	<u>Page</u>
6. EVALUATION OF STRUCTURAL STABILITY	
6.1 Visual Observations	6-1
6.2 Design and Construction Data	6-1
6.3 Post Construction Changes	6-1
6.4 Seismic Stability	6-1
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-1
7.4 Alternatives	7-2

#### APPENDICES

APPENDIX A - INSPECTION CHECKLIST


APPENDIX B - ENGINEERING DATA

APPENDIX C - PHOTOGRAPHS


APPENDIX D - HYDROLOGIC AND HYDRAULIC  
COMPUTATIONS

APPENDIX E - INFORMATION AS CONTAINED IN  
THE NATIONAL INVENTORY OF DAMS





5 0 5 10  
SCALE IN MILES



**TIGHE & BOND / SCI**  
**CONSULTING ENGINEERS**  
EASTHAMPTON, MASS.

**U.S. ARMY ENGINEER DIV. NEW ENGLAND**  
**CORPS OF ENGINEERS**  
WALTHAM, MASS.

**NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS**

## LOCUS PLAN I

**WASHINGTON MOUNTAIN LAKE DAM (MA 318)**  
**BERKSHIRE COUNTY**

**MASSACHUSETTS**

**SCALE: AS NOTED**

**DATE: DECEMBER 1979**

- 3) Silt in the left foundation drain pipe at the impact basin; misalignment also noted.
- 4) Broken pipe and misalignment of the right foundation drain at the impact basin.
- 5) Vehicular traffic on slopes of the emergency spillway.
- 6) The top of the dam at the spillway (right) end of the dam is lower than the design finish grade.
- 7) Debris in downstream flow conduit.
- 8) The apparent change in slope of the 20" pond drain pipe.
- 9) The damaged shaft on the pond drain operator and damaged concrete base. Also, missing nuts at the base of the operator.
- 10) Damaged concrete around the outlet pipe.
- 11) The guide berm at the left side of the emergency spillway discharge channel requires protection to prevent erosion.

(c) Appurtenant Structures

1) Inlet Structure At Pond Drain. (See Photos #6 & 7)

The inlet structure at the pond drain is in good condition. Some debris is caught on the trash rack.

The bottom release outlet pipe above the pond drain has a considerable amount of debris in it placed there by vandals. Also, the concrete repair around the pipe at the structure is rough and minor spalling is occurring.

The 20" pond drain pipe appears to be flat for about three pipelengths before it slopes to the riser.

2) Riser Structure and Normal Spillway (See Photo #2 & 8)

The riser structure and normal spillway is in good condition. Some areas of the concrete work are chipped from vandals. The grate covering the high stage weir opening has been damaged from vandals.

The crank shaft on the pond drain gate operator shows signs of damage due to use of a tool other than the proper crank to operate the gate. Also, two nuts are missing at the operator base and the concrete base is cracked.

3) Outlet Structure (See Photo #9)

The outlet structure is in generally good condition. Concrete has broken away from the structure completely around the end of the 30" conduit.

(d) Reservoir Area (See Photo #4)

The shore of the reservoir is shallow sloping and is stable.

(e) Downstream Channel

The downstream channel is a narrow channel passing over a shallow sloping area. The channel is stable and the area around the impact basin is in good condition.

3.2 Evaluation

The dam is in generally FAIR condition at this time. The foundation drain system is in POOR condition. The potential problems noted during the visual inspection are listed below:

- 1) Tire ruts on the top of dam are causing puddles and erosion.
- 2) Gravel in the foundation drain pipe located 365 feet left of the impact basin.



## SECTION 3 - VISUAL INSPECTION

### 3.1 Findings

#### (a) General

The Washington Mountain Lake Dam was in FAIR condition at the time of the inspection.

#### (b) Dam

##### 1) Earth Embankment (see photo #1, 10, 11 and 12)

The top of the dam has been traveled upon by vehicles and wheel ruts have developed. The ruts contain rainwater and continuous use as a road has caused erosion.

The foundation drain outlet which is about 365 feet to the left of the impact basin is a 4" AC pipe and is about 1/3 full of gravel that appears to have its source from within the pipe.

The foundation drains at the impact basin both show signs of damage.

The left drain pipe at the impact basin contains silt to about 1/4 the diameter which could have its source upstream in the foundation drain system. This drain pipe is also misaligned.

The right drain pipe is broken about 18" to 20" in from the end with a misalignment and gap between the broken sections. A smaller diameter plastic pipe has been inserted inside the AC pipe. The right drain did not show any flow even though the area above the impact basin, below the emergency spillway and adjacent to the toe of the dam was very wet. This drain could be plugged. The wet area appears to be ground water since there is no water impounded behind the dam.

##### 2) Emergency Spillway (See Photo #3)

The emergency spillway is in good condition. Some vehicular traffic on the slope of the spillway has caused ruts. The top of the dam at the spillway (right) end of the dam is 1.2 feet lower than the design finish grade. It appears that this portion of the dam was originally constructed to this lower elevation. The guide berm bordering the left downstream side of the spillway is not protected against erosion is not adequate along the berm and erosion will result when the spillway is functioning.

## SECTION 2 - ENGINEERING DATA

### 2.1 Design Data

Design data available from the Soil Conservation Service included hydrologic and hydraulic computations, structural computations, a geological report, soil laboratory test results, and embankment slope stability analysis computations. This data was reviewed and found to be substantially correct and valid. Therefore, it was used extensively in the computations presented in Section 5 and Appendix D of this report.

### 2.2 Construction Data

"As built" plans are available for this dam and show good agreement with the design plans and the visual inspection. Records show the top of dam and dike elevations to be the same (1,804.0 MSL). Because of the remoteness of the structures from each other, the elevations of the top were not verified in the field.

### 2.3 Operational Data

No operational data is available as the dam is self regulating and as of this date does not impound a normal pool of water.

### 2.4 Evaluation of Data

#### (a) Availability

Sufficient data is available to permit an evaluation of the dam when combined with findings of the visual inspection.

#### (b) Adequacy

There is sufficient design and construction data to permit an assessment of dam safety when combined with the visual inspection, past performance, and sound engineering judgment.

#### (c) Validity

Since the observations of the inspection team generally confirm the available data, a satisfactory evaluation for validity is indicated.

- b) Low stage inlet: 30.8 ft.
- c) High stage inlet: 15 ft.
- d) Emergency spillway: 50 ft.
- 3) Crest Elevation (ft. above MSL)
  - a) Pond drain inlet: 1771.0
  - b) Low stage inlet: 1797.98
  - c) High stage inlet: 1801.0
  - d) Emergency spillway: 1801.0
- 4) Gates: 20 inch vertical lift sluice gate on pond drain inlet
- 5) Upstream channel: Reservoir
- 6) Downstream channel: Narrow channel through gently sloping flood plain

(j) Regulating Outlet

The only regulating outlet is a 20 inch diameter reservoir drain pipe controlled by a crank operated sluice gate. The pipe invert is at elevation 1771.0 (MSL) at the drain inlet structure. The purpose of this outlet is pond drainage and it will be normally closed once a telephone cable in the pond area is relocated.

The gate is a Rodney Hunt, rising stem type, having the following identification:

28686-2  
S-5002-A

- 3) Spillway crest pool:
  - a) Low stage inlet: 224
  - b) High stage inlet: 243
  - c) Emergency spillway: 243
- 4) Test flood: Less than 256
- 5) Top of dam: 262

(g) Dam

- 1) Type: Earth embankment with riprap slope surface protection and earth cutoff trench
- 2) Length: 1145 ft.
- 3) Height: 34 ft.
- 4) Top width: 20 ft.
- 5) Side slopes: Upstream: 3 to 1  
Downstream: 2.5 to 1
- 6) Zoning: Homogeneous sand, silty with gravel and boulders, Foundation drain of drain fill.
- 7) Impervious core: None
- 8) Cutoff: Variable width, earthfill
- 9) Grout curtain: None

(h) Diversion and Regulating Tunnel

Not applicable

(i) Spillways

- 1) Type:
  - a) Principal spillway: Reinforced concrete drop inlet
  - b) Emergency spillway: Grass covered earth channel cut around the dam at the right abutment
- 2) Length of weir:
  - a) Pond drain inlet: 20 inch diameter pipe

6) Spillway crest:

- a) Pond drain inlet: 1771.0
- b) Low stage inlet: 1797.98
- c) High stage inlet: 1801.0
- d) Emergency spillway: 1801.0

7) Design surcharge: 1803.1

8) Top of dam: 1804.0

9) Test flood surcharge: 1,803.0

(d) Reservoir

- 1) Length of normal pool: 4,000± ft.
- 2) Length of flood control pool: 4,400± ft.
- 3) Length of emergency spillway crest pool: 4,400± ft.
- 4) Length of pool top of dam: 4,500± ft.
- 5) Length of test flood pool: 4,500±

(e) Storage (acre feet)

- 1) Normal pool: 3225
- 2) Flood control pool: 3910
- 3) Spillway crest pool:
  - a) Low stage inlet: 3225
  - b) High stage inlet: 3910
  - c) Emergency spillway: 3910
- 4) Top of dam: 4575
- 5) Test flood pool: 4325

(f) Reservoir Surface (acres)

- 1) Normal pool: 224
- 2) Flood control pool: 243

2) Maximum Known Flood

There is no data available for the maximum known flood at this damsite. Signs of debris on the embankment indicate that the water surface has been as high as at elevation 1793.0 (MSL).

3) Ungated Spillway Capacity at Top of Dam

The capacity of the principal spillway with the reservoir at top of dam elevation (1804 feet MSL) is 137.8 cfs. The capacity of the emergency spillway is 650 cfs at this level. The total capacity is, therefore, 788 cfs.

4) Ungated Spillway Capacity at Test Flood

The capacity of the principal spillway and the emergency spillway is not exceeded by the test flood and the dam is not overtopped. The discharge through the principal and emergency spillways at the test flood is about 600 cfs at an elevation of less than 1,803.

5) Gated Spillway Capacity at Normal Pool

There are no gated spillways with the exception of the gated pond drain inlet which would normally be closed when the dam impounds water.

6) Gated Spillway Capacity at Test Flood

As previously mentioned, there are no gated spillways.

7) Total Spillway Capacity at Test Flood

The total spillway capacity at test flood elevation is not exceeded and the dam is not overtopped. The total spillway discharge at test flood is about 600 cfs at an elevation of less than 1,803. The dam is safe from overtopping.

(c) Elevation (feet above MSL, NGVD)

- 1) Streambed at downstream toe of dam: 1760±
- 2) Bottom of cutoff: 1,762±
- 3) Maximum tailwater: unknown
- 4) Recreation pool: 1798±
- 5) Full flood control pool: 1801±

Commonwealth of Massachusetts  
Division of Forests and Parks  
Pittsfield State Forest  
Cascade Street  
Pittsfield, Massachusetts

Mr. Douglas G. Poland is the Regional Supervisor. The telephone number is 1-413-442-8992.

(g) Purpose of the Dam

The Washington Mountain Lake Dam is a multiple-purpose dam which maintains a low level recreation pool and provides flood water storage to reduce downstream flooding from the dam's drainage area. Stored flood water is gradually released through low and high level inlets of the principal spillway.

(h) Design and Construction History

The Washington Mountain Lake Dam was designed by the U.S. Department of Agriculture, Soil Conservation Service. The dam was built under the Watershed Protection and Flood Prevention Act by the Massachusetts Department of Natural Resources, which is currently the Department of Environmental Management, the Massachusetts Water Resources Commission, the Berkshire Conservation District and the Town of Lee, Mass.

(i) Normal Operating Procedure

The Washington Mountain Lake Dam is normally self regulating. The pond drain gate is operated only as part of infrequent maintenance checks. At the time of this inspection, the gate was open to preclude impoundment of water.

1.3 Pertinent Data

(a) Drainage Area

The drainage area for this dam covers approximately 1.3 square miles. It is made up primarily of rolling hill woodland.

(b) Discharge at Damsite

1) Outlet Works

Normal discharge at the site is through the 30 inch diameter outlet pipe. In the event of severe flooding, water would flow over the emergency spillway and the high stage orifice at elevation 1801.0 feet (MSL). The invert of the low stage weir is at elevation 1797.98 feet (MSL). The invert of the high stage weir is at elevation 1801.0 feet (MSL), which is equivalent to the emergency spillway elevation.

and end sill are provided to dissipate energy. Wing walls, opening to the brook channel, project from the end of the basin at a 45° angle and are 9.33 feet long.

3) Emergency Spillway (See Pg. B-15)

The emergency spillway was excavated in the right abutment. It curves to the left around the embankment and is 50 feet wide at the control section which was excavated in natural ground. It is approximately 500 feet long and lies approximately 3 feet below the crest of the dam. The side slopes are 2 horizontal to 1 vertical.

4) Foundation Drainage (See Pg. B-17)

A six foot wide foundation drain of fine drain fill extends the full length of the dam from 6 feet below the crest at the centerline on a 1.5 horizontal to 1 vertical to the original ground downstream. A 4" AC pipe bedded in coarse drain fill is provided at the toe of the drain to collect water and outlets at two locations, one through each sidewall of the reinforced concrete impact basin. A third drain outlets about 365 feet to the left of the impact basin centerline.

(c) Size Classification

The dam's maximum impoundment (computed to the top of the dam) of 4575 acre feet and height of 44 feet place it in the INTER-MEDIATE size category according to the Corps of Engineers' Recommended Guidelines.

(d) Hazard Classification

The hazard potential classification for this dam is HIGH because of the significant economic losses and potential for loss of life downstream which may occur in the event of dam failure. There is a high potential for severely damaging about 17 homes with possible loss of more than a few lives, as well as four roadway bridges and one railroad bridge.

(e) Ownership

The Washington Mountain Lake Dam is owned by the Commonwealth of Massachusetts, Division of Forests and Parks, 100 Cambridge Street, Boston, Massachusetts. They can be reached by telephone at 617-727-3180.

(f) Operator

The operation of the Washington Mountain Lake Dam is controlled by the Commonwealth of Massachusetts, Division of Forests and Parks. The regional office responsible for the dam is as follows:



the base, 15 inches from 3.5 feet to 11.6 feet, 12 inches from 11.5 feet to 21.5 feet and 10 inches for the remainder of height.

Eight feet above the base of the structure is a 20 inch diameter, vertical lift, sluice gate inlet which is controlled by a crank operated bench stand with a rising stem. A 20 inch diameter, reinforced concrete pond drain pipe extends 64 feet upstream from the lift gate into the impoundment pool area. A reinforced concrete inlet structure at the upstream end of this pipe is protected by a trash rack of galvanized steel angle bars placed on an incline across the opening.

The "low stage inlet" is an uncontrolled weir box approximately 35.6 feet above the 30" pipe invert. It is 30.8 feet long around three sides of the riser. The box is about 4 feet deep and 2.5 feet wide. The water flows over the riser weir box and flows through four orifices into the riser structure. It is protected by a trash rack assembly sloping from the weir box to the top of the riser. This assembly is fabricated from galvanized steel angle sections.

The "high stage inlet" consists of an opening at the top of the riser 2.5 feet by 7.5 feet. The opening is protected by a galvanized steel grating 4 feet by 8 feet.

The dam is provided with a 12" diameter bottom release outlet pipe extending from the inlet structure to the weir box. The purpose of this pipe is to provide downstream flow in the brook when the pool level is below the permanent pool weir. At the time of the inspection the bottom release outlet was set to operate when the lake was at normal pool elevation. The release outlet will be modified, according to Soil Conservation Service officials, to operate when the pool level is below the normal spillway crest. When this modification is completed, water from the lake bottom will be discharged to the brook downstream of the dam by way of the riser and conduit.

The riser structure is drained by a 30 inch diameter reinforced concrete pressure pipe. It is approximately 134.3 feet long and drops approximately 2.50 feet over that length. The pipe penetrates the downstream side of the riser structure and is supported by an 8-inch thick concrete cradle within the embankment. Plans indicate 4 concrete anti-seep collars cast around the pipe within the embankment.

The downstream end of the conduit and cradle extends into a reinforced concrete impact basin. The impact basin is 8 feet long along the axis of the dam, 11.5 feet wide normal to the axis of the dam and about 6.5 feet deep as measured from the top of the wall at the 30" pipe. The basin is 1.33 feet to the bottom below the 30" pipe invert. A baffle wall

State Rt. 20 to Becket Road, Becket Road to Tyne Road, Tyne Road to Yokum Pond Road, Yokum Pond Road to County Road, County Road to Lenox-Whitney Place Road and Lenox-Whitney Place Road to West Branch Road. The dam is shown on USGS East Lee, Massachusetts quadrangle at approximately coordinates N-42°-21.3', W-73°-12.1'. (See location map on page v). Sheets B-13 and B-14 of Appendix B is a site plan for this dam.

(b) Description of Dam and Appurtenances

The dam consists of an earth embankment with an earthfill cutoff trench below the embankment, a principal spillway with a reinforced concrete riser and outlet pipe, and an emergency spillway located at the right abutment. The length of the embankment is 1145 feet. The emergency spillway is 50 feet wide at the control section. An earth embankment dike, located approximately 3500 feet east of the dam, impounds water in conjunction with the dam. From available records, the elevation of top of the dike is the same as the top of the dam. The dike is the subject of a separate report (Washington Mountain Lake Dike, MA 00319).

1) Embankment (See pgs. B-15, B-16 and B-17)

The following information has been taken from the As-Built Drawings dated 1974.

The embankment is made up primarily of sand, silty with gravel and boulders with a maximum stone size of 6" in Zone 1 and 12" in Zone 2. It is 1145 feet long and is a maximum of 44 feet high. The upstream slope is 3 horizontal to 1 vertical; the downstream slope is 2.5 horizontal to 1 vertical; and the width of the crest is 20 feet.

Beneath the embankment is an earthfill cutoff trench of variable width at the bottom. According to available plans, it is constructed of the same material as Zone 1 of the embankment. The cutoff trench was designed and constructed to extend through disturbed top soil to glacial till.

2) Principal Spillway (See pgs. B-9, B-19, B-20, B-21 and B-22)

The principal spillway consists of a reinforced concrete drop inlet structure with a sluice gate controlled pond drain pipe, two permanent pool uncontrolled crest weirs and orifice inlets, two uncontrolled high stage weirs and an outlet pipe supported on a concrete cradle.

The riser structure is 38.5 feet high and 9.17 feet wide normal to the axis of the dam. The inside of the riser has an opening 2.5 feet long parallel to the embankment and 7.5 feet wide normal to the axis of the dam, which is the same size from the top of the riser to the invert. The walls of the riser are 18 inches thick for the first 3.5 feet from the top of

## PHASE I INSPECTION REPORT

### WASHINGTON MOUNTAIN LAKE DAM

#### SECTION 1

##### PROJECT INFORMATION

#### 1.1 General

##### (a) Authority

Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Tighe & Bond/SCI has been retained by the New England Division to inspect and report on selected dams in Massachusetts. Authorization and notice to proceed were issued to Tighe & Bond/SCI under a letter of October 24, 1979 from Colonel William E. Hodgson, Jr., Corps of Engineers. Contract No. DACW-33-80-C-005 has been assigned by the Corps of Engineers for this work.

##### (b) Purpose

- 1) Perform technical inspection and evaluation of non-federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-federal interests.
- 2) Encourage and prepare the states to initiate quickly effective dam safety programs for non-federal dams.
- 3) Update, verify, and complete the National Inventory of Dams.


##### (c) Scope

The Program provides for the inspection of non-federal dams in the high hazard potential category based upon location of the dams, and those dams in the significant hazard potential category believed to represent an immediate danger based on condition of the dams.

#### 1.2 Description of Project

##### (a) Location

The Washington Mountain Lake Dam is located in the watershed of Washington Mountain Brook approximately 3 miles upstream of the confluence of the Housatonic River and Washington Mountain Brook in Lee, Massachusetts. It can be reached by way of Mass.



- SCALE -  
1000' 0 1000' 2000' 3000'

FROM: U.S.G.S. EAST LEE, MASS.  
QUADRANGLE MAP



QUADRANGLE LOCATION

TIGHE & BOND / SCI  
CONSULTING ENGINEERS  
EASTHAMPTON, MASS.

U.S. ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASS.

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS

## LOCUS PLAN 2

WASHINGTON MOUNTAIN LAKE DAM ( MA 318 )  
BERKSHIRE COUNTY

MASSACHUSETTS

SCALE: AS NOTED

DATE: DECEMBER 1979

## SECTION 4 - OPERATIONAL AND MAINTENANCE PROCEDURES

### 4.1 Operational Procedures

No written operational procedures are available for this dam. The dam is normally self regulating.

### 4.2 Maintenance Procedures

An annual inspection is made by the Soil Conservation Service and recommendations resulting from this inspection are implemented by the Commonwealth of Massachusetts, Division of Forests and Parks (see copies of inspection reports in Appendix B).

### 4.3 Evaluation

There is need for an improved routine maintenance program as evidenced by the deficiencies noted during our visual inspection (see Section 3.2). There is no set schedule for operation of the sluice gate on the pond drain inlet; this sluice gate should be operated annually as a minimum and kept well lubricated to prevent corrosion and maintain the operator in an operable condition.

A formal, written, downstream emergency flood warning system should be developed for this dam.

## SECTION 5 - EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

### 5.1 General

The Washington Mountain Lake Dam is a Soil Conservation Service (SCS) flood control and recreation dam on Washington Mountain Brook in Washington, Massachusetts. The dam is about three miles upstream of the Town of Lee and 3 miles upstream of the confluence of Washington Brook and the Housatonic River. The upstream drainage area is 1.3 square miles with rolling hill topography.

The dam itself is a 1145 foot long earthen embankment with a grass-lined earth emergency spillway, 50 feet wide. The principal spillway consists of two weirs located on a concrete riser in the reservoir. Flow from the weirs proceeds under the dam through a 30" reinforced concrete pipe.

### 5.2 Design Data

The data sources available for Washington Mountain Lake Dam include the Soil Conservation Service's (SCS) "Hydrology and Hydraulics" Design Calculations. These calculations include Storage-Elevation and Stage-Discharge curves for the dam, and the routing of storms of various magnitudes through the reservoir. These calculations are dated 1971 and 1972.

Also available are Soil Conservation Service "As Built" plans dated 1973 and 1974.

The SCS established the elevation of the low stage outlet at 1797.98 feet MSL. The elevation of the high stage and emergency spillway (1801.0 feet MSL) was established at the 100-year flood stage in the reservoir. The top of dam (1804 feet MSL) was set slightly above the highest elevation of the Design High Water (1,803.1 MSL).

### 5.3 Experience Data

No records of flow or stage are known to be available for Washington Mountain Lake Dam, with the exception of debris on the upstream slope indicating the maximum level reached elevation 1793± MSL.

### 5.4 Visual Observations

The emergency spillway is a grass-lined earth channel, with its crest at 1801 feet MSL and 2:1 side slopes. Outflow from the emergency spillway does not feed into Washington Mountain Brook immediately. It runs through a minor channel and a shallow sloping area to the South before joining Washington Mountain Brook about 4,000 feet downstream. The principal spillway consists of a concrete riser structure in the reservoir with two weirs. The flow from these weirs combines in the

riser and flows under the dam through a 30 inch reinforced concrete pipe 134.33 feet long.

Downstream of the dam, Washington Mountain Brook runs about 8,000 feet before reaching the first development, three houses about 10 feet above the streambed. The brook passes under Washington Mountain Road, a lightly traveled road, through a bridge with a low chord 10.6 feet above the streambed.

For the next 2,000 feet Washington Mountain Brook parallels Washington Mountain Road to the north, until the brook passes under Woodland Road. Seven houses exist along the road and are 5 to 10 feet above the brook bed. The bridge on Woodland Road has a low chord of 5.5 feet above the brook bed.

The next 2,000 feet along Washington Mountain Brook impacts four houses and a house trailer that are less than 10 feet above the brook bed. Also, the stream passes under bridges on Washington Mountain Road, Mill Street and a railroad. The low chord of the bridge on Washington Mountain Road is 4 feet above the brook bed, the low chord of the Mill Street bridge is 3.33 feet above the brook bed and the low chord of the railroad bridge is 10.5 feet above the brook bed.

The brook then flows a few hundred feet across flood plain to the Housatonic River which has a drainage area of about 240 square miles above the point of confluence.

#### 5.5 Test Flood Analysis

The hydrologic conditions of interest in this Phase I investigation are those required to assess the dam's overtopping potential and its ability to safely allow an appropriately large flood to pass. This requires using the discharge and storage characteristics of the structure to evaluate the impact of an appropriately sized Test Flood. The original hydraulic and hydrologic design calculations of the SCS are available for this dam.

Guidelines for establishing a recommended Test Flood based on the size and hazard classification of a dam are specified in the "Recommended Guidelines" of the Corps of Engineers. The impoundment of between 1,000 and 50,000 acre feet and the height of less than 100 feet but more than 40 feet classify this dam as an INTERMEDIATE size structure.

The appropriate hazard classification for this dam is HIGH because of the significant economic losses and potential for loss of more than a few lives downstream in the event of dam failure.

As shown in Table 3 of the Corps of Engineers' "Recommended Guidelines," the appropriate Test Flood for a dam classified as INTERMEDIATE in size with a HIGH hazard potential would be the Probable Maximum Flood (PMF). The Maximum Probable Peak Flow Rate, given as the Corps of Engineers curve, assuming rolling topography is 2300 csm. The continuous flow of 2300 csm routed through the reservoir results in an outflow which does not exceed the combined spillway capacity. Therefore, the dam is safe from overtopping.

As part of their hydraulic and hydrologic design calculations for the dam, the SCS created a "Freeboard Hydrograph" and routed it through the reservoir using a storage router. The peak inflow is 10,601.2 cfs, which is 8154.7 csm on a 1.3 square mile drainage area. This, as compared to the 2300 csm given on the Corps of Engineers' "Maximum Probable Peak Flow Rates" curve assuming rolling topography, means the SCS design exceeds the Corps of Engineers MPF at peak flow period.

The SCS storage routing results in a peak outflow of 485 cfs, with the water surface at 1803± feet MSL, 1± foot below the dam crest and 5± feet above normal pool. This analysis assumes a starting water surface elevation of 1797.98 (MSL).

The combined spillway capacity is 788 cfs with water level at the crest of the dam.

#### 5.6 Dam Failure Analysis

The peak outflow that would result from the failure of Washington Mountain Lake Dam is estimated using the procedure suggested in the Corps of Engineers, New England Division's "Rule of Thumb Guidelines for Estimating Downstream Dam Failure Hydrographs." The procedure is carried out with dam failure occurring when the water surface is at the top of the dam (1804.0 MSL).

For an assumed breach width of 40% of the dam length at half height, the failure would be 120 feet wide. The resulting flood flow would be 58,900 cfs. Also, because it is assumed that breach of the dam would occur during a flood condition, the adjacent drainage area tributary to the Washington Mt. Brook will contribute a flow of about 18,000 cfs at the downstream impact areas.

Prior to the dam failure, the flow of 18,000 cfs from the drainage area will result in damage to five bridges and no more than two homes.

The first area to be impacted by the failure of the dam would be three houses and a bridge about 12,000 feet downstream. The bridge is on Washington Mt. Road and the houses are adjacent to the road near the bridge. The attenuated failure flow of 71,700 cfs would create a stage of 13.5 feet above the brook bed. This would cause shallow flooding at the houses but with the narrow reach the velocity would be high. Thus, there is a potential for loss of life and extensive property damage.

The next area to be impacted by the failure would be a reach about 2000 feet long where Washington Mountain Brook parallels Washington Mountain Road. At the end of the reach the brook passes under a bridge on Woodland Road. The attenuated failure flow of 70,200 cfs would create a stage of 7.5' above the brook bed.

The stage would cause extensive property damage to the seven houses along Washington Mountain Road in this reach and potential loss of life because of the high velocity flow around the houses.



The next reach is about 2000 feet long and the area to be impacted by the flood includes four houses, a house trailer, two road bridges and a railroad bridge. The attenuated failure flow of 69,000 cfs would cause a stage of 13.0 feet in this reach. In addition, because the railroad bridge cannot carry the flow, the railroad bed would be overtopped. Also flood water would overflow Mill Street to the south.


The flood flow over the railroad bed and Mill Street would have an estimated depth of 6 feet which would cause the depth of water at the railroad to be 18 feet above the brook bed.

The flood flow would cause extensive property damage and potential loss of life in this reach.

The next area impacted would be an area along Mill Street to the south where the flood water would overflow. This area contains two houses that would experience high velocity, shallow flooding as the water flows to the Housatonic River. There is a potential for loss of life and extensive property damage.

Once the failure flow passes the railroad bridge and Mill Street, the flow enters the Housatonic River. The peak dam failure flow of 69,000 cfs would be attenuated rapidly in the river channel.

The following table summarizes the downstream impacts of the failure of the Washington Mountain Lake Dam.



-SCALE-  
1000' 0 1000' 2000' 3000'

FROM: U.S.G.S. EAST LEE, MASS.  
QUADRANGLE MAP



TIGHE & BOND / SCI  
CONSULTING ENGINEERS  
EASTHAMPTON, MASS.

U.S. ARMY ENGINEER DIV. NEW ENGLAND  
CORPS OF ENGINEERS  
WALTHAM, MASS.

# NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS LOCATION AND DOWNSTREAM HAZARD MAP

WASHINGTON MOUNTAIN LAKE DAM (MA 318)  
BERKSHIRE COUNTY

MASSACHUSETTS

SCALE: AS NOTED

DATE: DECEMBER 1979

**Probable Downstream Impact of Dam Failure  
Washington Mountain Lake Dam**

<u>Location</u>	<u>No. of Houses Affected (After Dam Failure)</u>	<u>Other Damage (After Dam Failure)</u>	<u>Attenuated Flow (CFS) (Before Failure) (After Failure)</u>	<u>Brook Stage (Ft.) (Before Failure) (After Failure)</u>	<u>Comments</u>
1. Dam	0	0	18,000 58,900	--	No significant damage before dam failure
2. 12,000' Downstream of Dam at W. Mt. Rd.	3	1 bridge	18,000 71,700	6.5 13.5	Wash. Mt. Rd. is a secondary road. Before dam failure bridge in-undated.
3. 2,000' Downstream at Woodland Rd.	7	1 bridge	18,000 70,200	3.5 7.5	Woodland Rd. is a secondary road. Before dam failure bridge in-undated.
4. 2,000' Downstream at Railroad	4 1 (trailer)	1 R.R. bridge 2 Rd. bridges (Mill St. & W.M. Rd.)	18,000 69,000	6.5 13.0 (channel) 18.0 (R.R.)	R.R. line is major; Mill St. is a major road. Washington Mt. Road is a secondary road. Before dam failure, 2 road bridges & 1 R.R. bridge damaged.
5. Downstream of R.R. and Mill St.	2	0	18,000 69,000	5.0	Before dam failure, 2 houses experience shallow-high velocity flooding.

## SECTION 6 - EVALUATION OF STRUCTURAL STABILITY

### 6.1 Visual Observations

There has been no significant displacement or distress which would warrant the preparation of structural stability calculations.

### 6.2 Design and Construction Data

#### 1) Embankment

Analysis carried out during the design and construction phase included an embankment slope stability analysis by the Swedish circle method. Based on this analysis a 3 to 1 upstream slope and a 2.5 to 1 downstream slope were utilized.

#### 2) Appurtenant Structures

A review of the structural calculations for the design of the drop inlet service spillway structure and the outlet conduit (principal spillway) revealed that these structures have been designed on the basis of sound engineering practice.

### 6.3 Post Construction Changes

The only post construction modification of the Washington Mountain Lake Dam has been the addition of the bottom release outlet pipe. (See page B-26).

### 6.4 Seismic Stability

The Washington Mountain Lake Dam is located in seismic zone No. 2. According to the recommended Corps of Engineers guidelines, a seismic analysis is not warranted.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND  
REMEDIAL MEASURES

7.1 Dam Assessment

(a) Condition

The dam and its appurtenances are in FAIR condition due to the problems with the foundation drains.

(b) Adequacy of Information

There is sufficient design and construction data to permit an assessment of dam safety when combined with the visual inspection, past performance, and sound engineering judgment.

(c) Urgency

The recommendations and remedial measures described herein should be implemented by the owner within one year of receipt of this Phase I Inspector Report.

7.2 Recommendations

The recommendations of this Phase I Investigation are that the following additional studies be made under the supervision of a registered professional engineer:

- (a) Investigate the source of silt in the left and right toe drains which outlet at the impact basin and determine corrective measures including reconstruction or other remedial measures for the misaligned sections of these drains.
- (b) Investigate the source of the gravel and silt exiting from the toe drain pipe which outlets 365 feet left of the centerline of the outlet conduit and determine what corrective measures may be required.
- (c) Closely monitor the dam during and after initial filling of the upstream pool with particular attention to be paid to the foundation drainage system; instrumentation of the drainage outlets to monitor flows may be warranted.

7.3 Remedial Measures

It is recommended that the owner institute the following remedial and/or maintenance measures:

- a) Gravel the surface of the top of dam to prevent ruts and erosion if the crest is to be used as road. Otherwise, block off access to the top of dam to prevent trespassing.

- b) The top of the dam at the emergency spillway end of the dam should be filled so that the elevation at this point matches the design finish grade.
- c) Trespassing on the spillway slopes should be discouraged.
- d) Debris in the 12" bottom release outlet pipe should be removed and a screen placed over both ends to prevent continuing vandalism.
- e) The change in slope of the 20" drain pipe should be investigated and repairs made if required.
- f) The damaged shaft on the gate operator should be replaced, missing nuts replaced at the base and the concrete base repaired.
- g) The damaged concrete around the outlet pipe in the impact basin should be repaired to protect the reinforcing that is exposed.
- h) Implement and intensify a program of periodic maintenance including repairs to structures that are vandalized, prevention of trespassing on slopes and routine checks of the foundation drain systems.
- i) Operate the pond drain sluice gate at least annually as a maintenance check and keep the operator well lubricated.
- j) Prepare a formal written downstream emergency flood warning system.
- k) Continue the program of annual periodic technical inspections.

#### 7.4 Alternatives

There are no meaningful alternatives to the above recommendations.

APPENDIX A

Visual Check List With Comments

Act that the "Secretary [of the Army, acting through the Chief of Engineers] may issue permits, after notice and opportunity for public hearing for the discharge of dredged or fill material into the navigable waters at specified disposal sites."

1.7a To obtain permits for activities requiring them an applicant submits a form to the District office before beginning any work. Applicants furnish a detailed project description including drawings, lists of adjoining property owners and status of approvals or certifications required by other federal and state agencies. Once the application is received, it is acknowledged, processed and a public notice is issued. Normally, there is a 30-day comment period when federal, state and local agencies, individuals and special interest groups may review the application considering various environmental, and public interest factors. A public hearing may also be held during the 30-day period. All comments are then considered by the Corps in evaluating applications. If no serious objections or questions are raised, about 60 days are needed for the process. If the application is approved the applicant signs the document, returning it with a fee, and the permit is issued.

1.8 The Mobile District, Corps of Engineers has three administrative options available to it regarding the disposition of permit applications for structures and activities associated with oil and gas development projects. These are as follows:

- o Grant a permit as requested.
- o Grant a permit with restrictions or conditions.
- o Deny a permit.

#### INTENT, PURPOSE AND NEED FOR THE GENERIC ENVIRONMENTAL IMPACT STATEMENT

1.9 The District Engineer of the Mobile District, U.S. Army Corps of Engineers has determined that possible future development of hydrocarbon resources in the coastal areas of Alabama and Mississippi could potentially have a significant cumulative effect on the human environment, thereby requiring the preparation of an environmental impact statement under the provisions of the National Environmental Policy Act (NEPA). The intent of the study is to identify and consider the environmental effects that could result if permits are requested from and issued by the District for hydrocarbon resource development projects in the study area. These effects are to be considered in conjunction with hydrocarbon resource development activities that could occur in contiguous federal waters. The cumulative effects identified in this document must be considered in deliberations by the District Engineer for future permit applications.



## INSPECTION CHECK LIST

## PARTY ORGANIZATION

PROJECT Washington Mt. Lake DamDATE 11/2/79

MA 00318

TIME 8:30 A.M.WEATHER Cool and CloudyW.S. ELEV. 1771 U.S. 1760 D.N.S.PARTY:

- |                                                      |           |
|------------------------------------------------------|-----------|
| 1. <u>J.W. Powers, P.E., Proj. Manager</u>           | 6. _____  |
| 2. <u>G.H. McDonnell, P.E., Hydrology/Hydraulics</u> | 7. _____  |
| 3. <u>D.L. Lenart, P.E., Civil</u>                   | 8. _____  |
| 4. <u>E.A. Moe, P.E., Soils/Hydraulics</u>           | 9. _____  |
| 5. <u>H.A. Koski, Civil</u>                          | 10. _____ |

## PROJECT FEATURE

## INSPECTED BY

## REMARKS

- |                                                                     |  |
|---------------------------------------------------------------------|--|
| 1. <u>All project features were inspected by all party members.</u> |  |
| 2. _____                                                            |  |
| 3. _____                                                            |  |
| 4. _____                                                            |  |
| 5. _____                                                            |  |
| 6. _____                                                            |  |
| 7. _____                                                            |  |
| 8. _____                                                            |  |
| 9. _____                                                            |  |
| 10. _____                                                           |  |

## Also present:

R. Curran, U.S.D.A., Soil Conservation Service

C. Curtin, Massachusetts Division of Forests and Parks

## INSPECTION CHECK LIST

PROJECT Washington Mt. Lake DamDATE 11/2/79

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITIONS
<u>EMBANKMENT</u>	
Crest Elevation	1804.0 (Ruts from vehicles)
Current Pool Elevation	1771.0 (Intake invert)
Maximum Impoundment to Date	5'± below normal spillway elevation
Surface Cracks	None
Pavement Condition (riprap)	Upstream condition good Downstream condition good
Movement or Settlement of Crest	None (crest used for road) Some erosion noted in wheel ruts
Lateral Movement	None
Vertical Alignment	Good
Horizontal Alignment	Good
Condition at Abutment and at Concrete Structures	Right abutment good Left abutment good
Indications of Movement of Structural Items on Slopes	None
Trespassing on Slopes	Upstream slope good condition
Vegetation on Slopes	Downstream slope none apparent
Sloughing or Erosion of Slopes or Abutments	None
Rock Slope Protection - Riprap Failures	None
Unusual Movement or Cracking at or near Toes	None
Unusual Embankment or Downstream Seepage	None
Piping or Boils	None
Foundation Drainage Features	Left drain 4", open with slight flow 1/3 full gravel. Right drains 4", silt in pipe and damaged pipes. Channel at toe of dam in good condition.
Toe Drains	
Instrumentation System	None

AS-TRIAL  
22/76

OPERATION AND MAINTENANCE  
INSPECTION RECORD

U.S. Dept. of Agriculture  
Soil Conservation Service

Project WASHINGTON MOUNTAIN BROOK Inspection Date 5/27/76

Site Name/No. 3 (WASHINGTON MT LAKE) Type MULTIPURPOSE

Time of Inspection: Special ☐ Annual ☒ Structure Operation: Satisfactory ☐ Unsatisfactory ☐

Sponsoring Local Organization:

Present for Inspection: Edward Cahalan CARL L. CURTIN  
and Douglas W.R. Ronald Thompson, James Elmore

ITEM	Condi- tion * S or U	Maintenance & Needed Repairs	Esti- mated Costs	Agreed Dat- Repairs to be Complet
Vegetation	U	CROWN VETCH FERTILIZE 400# - 0-20-20 E.S. AND ADJACENT AREA FERTILIZE 400# - 15-15-15	2,000.	SEPT 30, 1976
Fences	S			
Principal Spillway	S			
Emergency Spillway	S	REMOVE BRUSH & FALLEN TREE	100.00	SEPT. 1976
Embankment & Riprap	S			
Reservoir Area	S	AREA BEING CLEARED		
Gates or Valves	S			
Outlet Channels	S			
Structure Drainage Outlets	S	REMOVE LOGS + brush INSTALL RODENT GUARD - DRAIN PIPE	100.00	SEPT 1976
Access Rd.	S	REGRADE AND USE GRAVEL WHERE NECESSARY		SEPT 1976
Spill Area	S	CUSHED STONE IN THREE AREA (1 LOAD)	150.00	SEPT 1976

REMARKS: (over) \* S = Satisfactory; U = Unsatisfactory

When cleaning contract complete, rescut top of dam and replace gate.

W. Thompson James Elmore Edward Thompson  
District Conservationist Project Engineer (Site Engineer)  
Report due annually: July 1

UNITED STATES DEPARTMENT OF AGRICULTURE

SOIL CONSERVATION SERVICE

29 Cottage Street, Amherst, Massachusetts

Date: June 2, 1976

SUBJECT: AS - Distribution of Operation and Maintenance Inspection Report/s  
(PL 566)

TO: 1. Charles Kennedy (2 copies),  
Director and Chief Engineer  
Division of Water Resources  
Mass. Dept. of Environmental Mgt.  
100 Cambridge Street  
Boston, MA 02202

Bette Woody, Commissioner  
Mass. Dept. of Environmental Mgt  
100 Cambridge St.  
Boston, MA 02202

2. Soil Conservation Service  
District Conservationist/s  
R. Thompson  
Project Engineer  
Elasmar  
State Administrative Officer  
(file copy)  
State Conservation Engineer

Chairman, Board of Selectmen  
Town Hall  
Lee, Mass. 01238

Chairman, Berkshire Cons. District  
c/o Pittsfield SCS

C. Curtin  
Mass. Div. of Forests and Parks  
Pittsfield State Forest  
Cascade Street  
Pittsfield, MA 01201

Enclosed are reports of the O&M inspection held in the Washington Mt. Brook  
for the sites listed below: (watershed)

<u>Site</u>	<u>Date Inspection Performed</u>
Washington Mountain Lake	5/27/76

Sincerely,

*(Signature)*  
Dr. Benjamin Isgur, Atty.  
State Conservationist

/ Enclosure/s



NO. AS-TRIAL: 2  
5/2/76

OPERATION AND MAINTENANCE  
INSPECTION RECORD

U.S. Dept. of Agriculture  
Soil Conservation Service

Project WASHINGTON MOUNTAIN BROOK W/S Inspection Date 5/10/77

Site Name/No. WASH. MOUNTAIN LAKE Type MULTI-PURPOSE

Type of Inspection: Special ☐ Annual ☒ Structure Operation: Satisfactory ☒ Unsatisfactory ☐

Sponsoring Local Organization: BERKSHIRE CONSERVATION DISTRICT, W.R.C.

Present for Inspection: (1) Ernest Stutzman Ron Thompson

James Elmore

ITEM	Condi- tion S or U	Maintenance & Needed Repairs	Esti- mated Costs	Agreed Date Repairs to be Complete
1. Vegetation	U	LIME + FERTILIZE 10-10-10, 1400* per acre	2,000	Sept. 1977
2. Fences	S			
3. Principal Spillway	S			
4. Emergency Spillway	S	Remove dead spruce tree & brush	100.00	Sept 1977
5. Embankment & Riprap	S	Place gravel top of dam - Remove growth, D/S slope + put net. 2-4-D	1,500.00	Sept 1977
6. Reservoir Area	S	Remove brush edge of water	500.00	Sept 1977
7. Gates or Valves	S			
8. Outlet Channels	S			
9. Structure Drainage Outlets	S	Remove brush. Install animal guard (bar pipe)	150.00	Sept 1977
10. Access Rd.	S			
11. Spillway	S			

REMARKS: (over)

S = Satisfactory; U = Unsatisfactory

Paul E. Thompson  
(District Conservationist)

James Elmore  
(Project Engineer)

Ernest Stutzman  
(SLO Representative)

(Report due annually: July 1)

WA-5-TRIAL  
5/22/76

OF TION AND MAINTENANCE  
INSPECTION RECORD

S. Dept. of Agriculture  
Soil Conservation Service

Project Washington Mountain Brook Inspection Date 8/17/1978

Site Name/No. Wash. Mount. Lake Type Multi-Purpose

Type of Inspection: Special ☐ Annual ☒ Structure Operation: Satisfactory ☒ Unsatisfactory ☐

Sponsoring Local Organization: Berkshire Conservation Dist. WRC.

Present for Inspection: Edward C. Carlson, Sup. District, U.S. Forest, P. Service  
Wm. M. Murray, Chief of Section, T. Doane, Jr., I.D. P. R.  
Donald Thompson, D.C., Ray Curran, James Elasmir, SCS

ITEM	Condi- tion * S or U	Maintenance & Needed Repairs	Esti- mated Costs	Agreed Date Repairs to be Complete
1. Vegetation	S	LIME, FERTILIZER TOP DRESS, 3 TON/LAKE 10-10-10,	2500-	SEPT 30, 1978
2. Fences	S			
3. Principal Spillway	S			
4. Emergency Spillway	S			
5. Embankment & Riprap	S	RIKE, PULL HARMFUL OLD VEGETATION ON SLOPES, OR CUT + TREAT W/2-4-D HERBICIDE. CUT + TREAT W/2-4-D HERBICIDE SLOPES OF DAM	2,000 -	OCT 30, 1978
6. Reservoir Area	S			
7. Gates or Valves	S			
8. Outlet Channels	S	REMOVE GROWTH CHANNEL + SLOPES	500 -	OCT 30, 1978
9. Structure Drainage Outlets	S	INSTALL ANIMAL GUARD AT DRAIN PIPE (SEEP HOLE TO BE PLUGGED)	200 -	OCT 30, 1978
10. Access Rd.	S	Needs grading	650 -	OCT 30, 1978
11. SPILL AREA	S			

REMARKS: (over) S = Satisfactory; U = Unsatisfactory

Donald Thompson (District Conservationist)  
James Elasmir (Project Engineer)  
(Report due annually: July 1)

Thomas P. Doane, Jr.  
(SLO Representative)

OHIO CONSERVATION SERVICE  
STATE OF OHIO

OPERATION AND MAINTENANCE  
INSPECTION RECORD

U-15/U-16  
(Prelim File)  
Revised 9/79  
File Code 52-11-15

Location: WASHINGTON MOUNTAIN BROOK W/S Inspection Date: 10/15/79

Name/No. WASH MTH LAKE Purpose MULTI-PURPOSE

Type of Inspection: Special ☐ Annual ☒ Structure Operation: Satisfactory ☒ Unsatisfactory ☐

Sponsoring Local Organization: BERKSHIRE CONSERVATION DIST N.Y.C.

Present for Inspection: TED CAHALAN, D.C. CURTIN, DENGT - EP. STRUBBIE, W. RY. CURRAN, GARY PARKER - S.C.S., W.M. MURPHY, LEE, J. EGAN - EAGLE, P. SCOLFE, DICK LEE, MARIA BETTEGA - Chm. Bd. Schickman

ITEM	Condition * (S or U)	Maintenance & Needed Repairs	Estimated Costs	Agreed Date Repairs to be completed
1. Vegetation	S			
2. Fences	-			
3. Principal Spillway	S			
4. Emergency Spillway	S			
5. Embankment & Riprap	S	PLACE GRAVEL ON TOP OF DAM & FILL & SEED REMOVE HARDWOOD GROWTH ON DIKE	1000-	MAY 1980
6. Reservoir Area	S			
7. Gates and Weirs	S			
8. Outlet Channels	S	REMOVE GROWTH ON CHANNEL SLOPES	1300-	MAY '80
9. Structure Drainage Outlets	S			
10. Access Rd.	S	MINOR GRADING	250-	MAY '80
11.				

REMARKS: (over)

S = Satisfactory; U = Unsatisfactory

[Signature] District Conservationist  
[Signature] District Engineer

3. <u>Drawings</u>	<u>Title</u>	<u>Page No.</u>
1	Cover Sheet	B-12
2	Plan of Storage Area	B-13
3	Plan of Storage Area	B-14
5	Plan of Damsite and Emer. Spillway	B-15
6	Fill Placement	B-16
8	Dam Foundation Drain Details	B-17
9	Principal Spillway ~ Plant Profile	B-18
13	Riser Details	B-19
19	Conduit Details	B-20
20	Reservoir Drain Inlet Details	B-21
21	Impact Basin Details	B-22
27, 28, 29	Logs of Test Holes	B-23-25
1 of 1	Riser Modification (Bottom Release)	B-27



## APPENDIX B

### ENGINEERING DATA

#### INDEX

#### 1. Design and Construction Records

The following records are kept on file by the US Department of Agriculture, Soil Conservation Service, and may be obtained through their office located on Cottage Street in Amherst, Massachusetts.

Design records include the following:

- construction drawings
- construction specifications
- construction revisions
- design criteria
- layout
- hydraulic design
- foundation and embankment design
- geology report
- soil testing report
- structural computations
- quantity estimates
- inspector's notes
- seeding schedule

Construction records include the following:

- inspector's and engineer's diaries
- soil testing reports
- concrete testing reports
- material certifications
- equipment guarantees
- correspondence
- quantities
- pay estimates
- "As Built" drawings

#### 2. Prior Inspection Reports

<u>Date</u>		<u>Page No.</u>
10/15/79	Soil Conservation Service Annual Report	B-1
8/17/78	Soil Conservation Service Annual Report	B-2
5/10/77	Soil Conservation Service Annual Report	B-3
6/2/76	Soil Conservation Service Annual Report	B-4
6/5/75	Soil Conservation Service Annual Report	B-7
6/12/75	Soil Conservation Service Annual Report	B-8
7/2/74	Soil Conservation Service Annual Report	B-11

APPENDIX B  
ENGINEERING DATA

## INSPECTION CHECK LIST

PROJECT Washington Mt. Lake DamDATE 11/2/79

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

## AREA EVALUATED

## CONDITION

OUTLET WORKS - SERVICE BRIDGE

## a. Super Structure

Bearings

Anchor Bolts

Bridge Seat

Longitudinal Members

Under Side of Deck

Secondary Bracing

Deck

Drainage System

Railings

Expansion Joints

Paint

N/A

## b. Abutment &amp; Piers

General Condition of Concrete

Alignment of Abutment

Approach to Bridge

Condition of Seat &amp; Backwall

## INSPECTION CHECK LIST

PROJECT Washington Mt. Lake DamDATE 11/2/79

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - INTAKE CHANNEL AND</u> <u>INTAKE STRUCTURE</u>	
a. Approach Channel	Good condition (brook good)
Slope Conditions	Good
Bottom Conditions	Stone and gravel
Rock Slides or Falls	None
Log Boom	None
Debris	Some debris on trash rock
Condition of Concrete Lining	Pipe in good condition. Slope flat for 3 lengths, some debris in upper conduit
Drains or Weep Holes	N/A
b. Intake Structure	
Condition of Concrete	Good but rough patch around downstream flow conduit.
Stop Logs and Slots	N/A
Trash rock	Both bars of trash rock in good condition

## INSPECTION CHECK LIST

PROJECT Washington Mt. Lake DamDATE 11/2/79

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - CONTROL TOWER</u>	
a. Concrete and Structural	
General Condition	Good but some vandalism
Condition of Joints	Good
Spalling	Some chips from vandals
Visible Reinforcing	None
Rusting or Staining of Concrete	Some rust stain on L & R sides
Any Seepage or Efflorescence	Some on left side of tower
Joint Alignment	Good
Unusual Seepage or Leaks in Gate Chamber	None
Cracks	None noted from limit of inspection
Rusting or Corrosion of Steel	Some slight amount on grouting
b. Mechanical and Electrical	
Air Vents	N/A
Float Wells	N/A
Crane Hoist	N/A
Elevator	N/A
Hydraulic System	N/A
Service Gates	Rodney Hunt 28686-2 S-5002-A
Emergency Gates	Concrete cracked at base of operator. Two of four bolts loose (anchor).
Lightning Protection System	None
Emergency Power System	None
Wiring and Lighting System in Gate Chamber	None

## INSPECTION CHECK LIST

PROJECT Washington Mt. Lake Dam :DATE 11/2/79

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u>  General Condition of Concrete  Rust or Staining on Concrete  Spalling  Erosion or Cavitation  Cracking  Alignment of Monoliths  Alignment of Joints  Numbering of Monoliths	No access to transition ; could not inspect

## INSPECTION CHECK LIST

PROJECT Washington Mt. Lake DamDATE 11/2/79

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u>	
General Condition of Concrete	Fair
Rust or Staining	None
Spalling	Concrete has spalled in a ring around outlet pipe
Erosion or Cavitation	None
Visible Reinforcing	Where concrete spalled around outlet
Any Seepage or Efflorescence	None
Condition at Joints	Good
Drain holes	Below water in basin; condition not known
Channel	
Loose Rock or Trees Overhanging Channel	None
Condition of Discharge Channel	Good

## INSPECTION CHECK LIST

PROJECT Washington Mt. Lake DamDATE 11/2/79

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS</u></p> <p>a. Approach Channel</p> <p>General Condition</p> <p>Loose Rock Overhanging Channel</p> <p>Trees Overhanging Channel</p> <p>Floor of Approach Channel</p> <p>b. Weir and Training Walls</p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Any Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Drain Holes</p> <p>c. Discharge Channel</p> <p>General Condition</p> <p>Loose Rock Overhanging Channel</p> <p>Trees Overhanging Channel</p> <p>Floor of Channel</p> <p>Other Obstructions</p>	<p>Good</p> <p>Right slope has some ledge</p> <p>None</p> <p>Good grade</p> <p>Crest good slopes show vehicular traffic. Crest 51' wide.</p> <p>N/A</p> <p>N/A</p> <p>N/A</p> <p>N/A</p> <p>N/A</p> <p>N/A</p> <p>Good condition</p> <p>Good condition</p> <p>None</p> <p>Trees at end</p> <p>Good grass growth</p> <p>None</p> <p>Top of slope at end of dam is 1.3' below crest</p>



Ordnance Dept

Dist of Washington Mt Lake & Area

Washington Mt Lake

1. Tenny Lee (Chairman, Board of  
Selectmen)
2. Berkshire Co. Dist. (Chairman)  
c/o Pittsfield R.S.
3. C. Kennedy, Dist of Water Res. Dist
4. Commissioner Mass Dept of  
Envl Mgt (Woolly) <sup>(Beale)</sup>
5. ~~State~~ District Conservation (Thompson)  
(Pittsfield field office)
6. Reg Engr - Area - Elmore
7. A. Veris Dean - "original"
8. (Curran) State Cons Engr / Engr field
9. Attendees
10. Route copy to Miller/Chapman/Monahan  
- Ingers
11. <sup>Dist</sup> Forest & Parks James Lambert Engr District  
(and 10000 Engr District (Pittsfield))

June 5, 1975

REPORT OF ANNUAL INSPECTION

WASHINGTON MOUNTAIN BROOK WATERSHED

On June 4, 1975, the following met at the Washington Mountain Lake Site, Washington Mountain Brook Watershed in the town of Washington, Massachusetts for the purpose of conducting the annual inspection.

Ernest Struzziero  
Douglas Poland  
Carl Curtin  
Rick DeVergilio  
James J. Elasmar

Water Resources Commission-Boston  
Department of Natural Resources-Pittsfield  
Department of Natural Resources-Pittsfield  
Soil Conservation Service-Pittsfield  
Soil Conservation Service-Otis

General

The Massachusetts Department of Natural Resources is responsible for the operation and maintenance of this site.

Structural Conditions and Recommendations

1. Remove debris from inlet channel.
2. Remove logs and debris from inlet channel.
3. Clean out silt from inlet channel.
4. Replace animal guard, outlet of drain at impact basin.
5. Clean out 4" drain outlets at impact basin.
6. Clean out 2 culverts under Navin Road leading away from toe drain.
7. Replace barricade cable at Jam.

Douglas Poland and Carl Curtin suggested that large boulders be placed as a barricade in lieu of the cable.

The riprap at the outlet looks very good.

Report on Agronomic conditions will be submitted by Ronald Thompson.

Submitted by:

*James J. Elasmar*  
James J. Elasmar  
Project Engineer  
Otis, Ma.

June 12, 1975

REPORT OF ANNUAL INSPECTION  
WASHINGTON MOUNTAIN BROOK WATERSHED

On June 5, 1975, the following met at the Washington Mountain Lake Site, Washington Mountain Brook Watershed in the Town of Washington, Massachusetts for the purpose of conducting the annual inspection.

Jim Elasmir	Soil Conservation Service-Otis
Ernest Stuzzerio	Water Resources Commission-Boston
Carl Curtin	Department of Natural Resources-Pitts.
Doug Poland	Department of Natural Resources-Pitts.
Rick DeVergilio	Soil Conservation Service-Pittsfield

GENERAL

The Massachusetts Department of Natural Resources is responsible for the operation and maintenance of this site.

Agronomic Conditions and Recommendations: (6-5-75)

The top of the dam is being used as a roadway. Very little vegetation is established on this area. A reseeding of the dam top is needed.

Erosion is taking place within the roadway along the southeast side of the spillway. Water diverting and reseeding is needed. The area in general should be closed to vehicular traffic.

A fallen tree needs to be removed from spillway. Spillway and other seeded areas should be mowed once a year.

Some erosion is taking place just west of outlet.

Vehicular traffic is causing some erosion upon side slope of spoil area.

Submitted by:

Richard DeVergilio  
Soil Conservationist  
SCS, Pittsfield, Mass.

rrk

Recommendations:

Vegetated areas should be limed with 3 tons/acre and fertilized with 400 lbs of 5-10-10/acre. Areas being used as roads should be reseeded. Also, the erosion taking place at the left end of the spillway should be corrected. Seeding mixtures should be equivalent to that originally specified.

Submitted by:

*R. E. Thompson*

R. E. Thompson,  
District Conservationist  
SCS, Pittsfield, Mass.

rrk

cc: James Elasmr, Otis

West of ...  
 Kept till 6/5/75  
 6/12/75

Warden from Nat Bureau to ...  
 7/3/75

Final

- 1 ✓ James G. Lee (Board of Selection)
- 2 ✓ J. B. ... (Chairman)
- 3 ✓ ... (Chairman)
- 6 ✓ ... (Chairman)
- 8 ✓ E. ... (original) please for ...
- 9 ✓ ...
- 10 ✓ ... (Chairman)
- 11 ✓ ... (Thompson)
- 12 ✓ ...
- 13 ✓ ...
- 14 ✓ ...
- 15 ✓ ...
- 16 ✓ ...
- 17 ✓ ...
- 18 ✓ ...

...  
 ...  
 ...

...  
 ...  
 ...

July 2, 1974

REPORT OF ANNUAL INSPECTION  
WASHINGTON MOUNTAIN BROOK WATERSHED

On June 27, 1974, the following met at the Washington Mountain Lake Site, Washington Mountain Brook Watershed in the Town of Washington, Massachusetts for the purpose of conducting the annual inspection.

Bruno Cadenelli  
Kevin Maguire  
William Annable  
James J. Elasmar

Department of Natural Resources  
Water Resources Commission-Boston  
Soil Conservation Service-Amherst  
Soil Conservation Service-Otis

GENERAL

The Massachusetts Department of Natural Resources is responsible for the operation and maintenance of this site.

Structural Conditions and Recommendations

Clear debris from inlet channel.  
Remove fallen tree from Emergency Spillway.  
Remove excess mulch left side of Emergency Spillway.  
Replace animal guard, outlet of drain at impact basin.  
Clean out 4 drain outlets at impact basin.  
Replace barricade cable at dam.  
Clean out 2 culverts under Navin Road leading away from the toe drain at the dike.

The condition of the concrete and the riprap at the outlet channel looks good.

Agonomic Conditions and Recommendations: (8/14/74)

The top of the dam is being used as a road which has resulted in the loss of vegetation. The spillway needs to be mowed and one fallen tree removed. The entire seeded area should be limed with two tons of lime and fertilized with 400 pounds of 5-10-10.

Some erosion is taking place to the left of the spillway at the end. This is being caused by vehicular traffic.

The trash rack needs cleaning and sediment needs to be removed.

Submitted by:



James J. Elasmar  
Project Engineer

R. Thompson  
District Conservationist  
SCS, Pittsfield, Mass.

<p> DRAINAGE AREA  TOTAL STORAGE  FLOODWATER RETAINING STORAGE  TO EMERGENCY SPILLWAY CREST  WATER SURFACE AREA  HEIGHT OF DAM  VOLUME OF FILL </p>	<p> 832 ACRES  3910 ACRE FEET  685 ACRE FEET  224 ACRES  34 FEET  70,000 CUBIC YARDS </p>
-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------

**BUILT UNDER THE WATERSHED PROTECTION AND  
FLOOD PREVENTION ACT**

by  
MASSACHUSETTS DEPARTMENT OF NATURAL RESOURCES

and  
MASSACHUSETTS WATER RESOURCES COMMISSION

**and**  
**BERKSHIRE CONSERVATION DISTRICT**

**TOWN OF LEE**  
**of the**

COMMONWEALTH OF MASSACHUSETTS

**with the assistance of**

## SOIL CONSERVATION SERVICE


of the

UNITED STATES DEPARTMENT OF AGRICULTURE

1972


## INDEX

Sheet 1 - COVER SHEET	Sheet 12 - MAIN ROAD DISE FOUNDATION DRAIN	Sheet 23 - IMPACT BASIN DETAILS
Sheet 2 - PLAN OF STORMAGE AREA	Sheet 13 - RISER DETAILS	Sheet 24 - IMPACT BASIN DETAILS
Sheet 3 - PLAN OF STORMAGE AREA	Sheet 14 - RISER DETAILS	Sheet 25 - IMPACT BASIN DETAILS
Sheet 4 - TRIANGULAR STORMAGE AREA	Sheet 15 - RISER DETAILS	Sheet 26 - IMPACT BASIN DETAILING & RAIL FENCE DETAILS
Sheet 5 - PLAN OF EMERGENCY SPILLWAY	Sheet 16 - RISER DETAILS	Sheet 27 - LOGS OF TEST HOLES
Sheet 6 - FILL PLACEMENT	Sheet 17 - RISER DETAILS	Sheet 28 - LOGS OF TEST HOLES
Sheet 7 - DAM CUTOFF TRENCH PROFILE	Sheet 18 - RISER TRASH RACK DETAILS	Sheet 29 - LOGS OF TEST HOLES
Sheet 8 - DAM FOUNDATIONS BEHIND WEIRBANK	Sheet 19 - GROUT DETAILS	Sheet 30 - STABILIZATION OF STRUCTURES
Sheet 9 - SPILLWAY SPILLWAY - PLAN & ELEVATIONS	Sheet 20 - WEIRBANK DRAIN INLET DETAILS	Sheet 31 - STABILIZATION OF STRUCTURES
Sheet 10 - SPILLWAY SPILLWAY - PLAN & ELEVATIONS	Sheet 21 - IMPACT BASIN DETAILS	
Sheet 11 - MAIN ROAD DISE PLAN & CUTOFF TRENCH PROFILE	Sheet 22 - IMPACT BASIN DETAILS	



WASHINGTON MOUNTAIN BROOK WATERSHED PROJECT WASHINGTON MOUNTAIN LAKE MULTIPLE-PURPOSE DAM OCTOBER MOUNTAIN STATE FOREST, MASSACHUSETTS	COVER SHEET	U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	Approved for publication by the Director Date: 10/1/73 Approved by the State Engineer Date: 10/1/73 Approved by the State Forester Date: 10/1/73
----------------------------------------------------------------------------------------------------------------------------------------------	-------------	-------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------

# Design B-12







WASHINGTON MOUNTAIN BROOK WATERSHED PROJECT  
WASHINGTON MOUNTAIN LAKE MULTIPLE-PURPOSE DAM  
OCTOBER MOUNTAIN STATE FOREST, MASSACHUSETTE


### PLAN OF STORAGE AREA

U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Shipped	J A TACKETT C H 80006	Date	8/17
Drawn	P J 8110A	8/18/77	
Filled	P J 8110A	8/18/77	
Checked	P J 8110A C H 80006	8/18/77	

Approved By \_\_\_\_\_  
 Title \_\_\_\_\_  
 Date \_\_\_\_\_

MA-361P



## CONSTRUCTION NOTES

1. Mr. J. Edgar Hoover  
 2. Director  
 3. Federal Bureau of Investigation  
 4. Washington, D. C.  
 5. Dear Sir:  
 6. I am writing you to inform you that  
 7. the following information was received  
 8. from the New York Office on  
 9. October 10, 1935:  
 10. On October 10, 1935, the New York  
 11. Office received information from  
 12. the New York City Police Department  
 13. that a person known as  
 14. John Doe, who is known to be  
 15. a member of the New York City  
 16. Police Department, had been  
 17. seen at the New York City  
 18. Police Department on October 10,  
 19. 1935.  
 20. Very truly yours,  
 21. J. Edgar Hoover  
 22. Director  
 23. Enclosure  
 24. Very truly yours,  
 25. J. Edgar Hoover  
 26. Director  
 27. Enclosure  
 28. Very truly yours,  
 29. J. Edgar Hoover  
 30. Director  
 31. Enclosure  
 32. Very truly yours,  
 33. J. Edgar Hoover  
 34. Director  
 35. Enclosure  
 36. Very truly yours,  
 37. J. Edgar Hoover  
 38. Director  
 39. Enclosure  
 40. Very truly yours,  
 41. J. Edgar Hoover  
 42. Director  
 43. Enclosure  
 44. Very truly yours,  
 45. J. Edgar Hoover  
 46. Director  
 47. Enclosure  
 48. Very truly yours,  
 49. J. Edgar Hoover  
 50. Director  
 51. Enclosure  
 52. Very truly yours,  
 53. J. Edgar Hoover  
 54. Director  
 55. Enclosure  
 56. Very truly yours,  
 57. J. Edgar Hoover  
 58. Director  
 59. Enclosure  
 60. Very truly yours,  
 61. J. Edgar Hoover  
 62. Director  
 63. Enclosure  
 64. Very truly yours,  
 65. J. Edgar Hoover  
 66. Director  
 67. Enclosure  
 68. Very truly yours,  
 69. J. Edgar Hoover  
 70. Director  
 71. Enclosure  
 72. Very truly yours,  
 73. J. Edgar Hoover  
 74. Director  
 75. Enclosure  
 76. Very truly yours,  
 77. J. Edgar Hoover  
 78. Director  
 79. Enclosure  
 80. Very truly yours,  
 81. J. Edgar Hoover  
 82. Director  
 83. Enclosure  
 84. Very truly yours,  
 85. J. Edgar Hoover  
 86. Director  
 87. Enclosure  
 88. Very truly yours,  
 89. J. Edgar Hoover  
 90. Director  
 91. Enclosure  
 92. Very truly yours,  
 93. J. Edgar Hoover  
 94. Director  
 95. Enclosure  
 96. Very truly yours,  
 97. J. Edgar Hoover  
 98. Director  
 99. Enclosure  
 100. Very truly yours,  
 101. J. Edgar Hoover  
 102. Director  
 103. Enclosure  
 104. Very truly yours,  
 105. J. Edgar Hoover  
 106. Director  
 107. Enclosure  
 108. Very truly yours,  
 109. J. Edgar Hoover  
 110. Director  
 111. Enclosure  
 112. Very truly yours,  
 113. J. Edgar Hoover  
 114. Director  
 115. Enclosure  
 116. Very truly yours,  
 117. J. Edgar Hoover  
 118. Director  
 119. Enclosure  
 120. Very truly yours,  
 121. J. Edgar Hoover  
 122. Director  
 123. Enclosure  
 124. Very truly yours,  
 125. J. Edgar Hoover  
 126. Director  
 127. Enclosure  
 128. Very truly yours,  
 129. J. Edgar Hoover  
 130. Director  
 131. Enclosure  
 132. Very truly yours,  
 133. J. Edgar Hoover  
 134. Director  
 135. Enclosure  
 136. Very truly yours,  
 137. J. Edgar Hoover  
 138. Director  
 139. Enclosure  
 140. Very truly yours,  
 141. J. Edgar Hoover  
 142. Director  
 143. Enclosure  
 144. Very truly yours,  
 145. J. Edgar Hoover  
 146. Director  
 147. Enclosure  
 148. Very truly yours,  
 149. J. Edgar Hoover  
 150. Director  
 151. Enclosure  
 152. Very truly yours,  
 153. J. Edgar Hoover  
 154. Director  
 155. Enclosure  
 156. Very truly yours,  
 157. J. Edgar Hoover  
 158. Director  
 159. Enclosure  
 160. Very truly yours,  
 161. J. Edgar Hoover  
 162. Director  
 163. Enclosure  
 164. Very truly yours,  
 165. J. Edgar Hoover  
 166. Director  
 167. Enclosure  
 168. Very truly yours,  
 169. J. Edgar Hoover  
 170. Director  
 171. Enclosure  
 172. Very truly yours,  
 173. J. Edgar Hoover  
 174. Director  
 175. Enclosure  
 176. Very truly yours,  
 177. J. Edgar Hoover  
 178. Director  
 179. Enclosure  
 180. Very truly yours,  
 181. J. Edgar Hoover  
 182. Director  
 183. Enclosure  
 184. Very truly yours,  
 185. J. Edgar Hoover  
 186. Director  
 187. Enclosure  
 188. Very truly yours,  
 189. J. Edgar Hoover  
 190. Director  
 191. Enclosure  
 192. Very truly yours,  
 193. J. Edgar Hoover  
 194. Director  
 195. Enclosure  
 196. Very truly yours,  
 197. J. Edgar Hoover  
 198. Director  
 199. Enclosure  
 200. Very truly yours,  
 201. J. Edgar Hoover  
 202. Director  
 203. Enclosure  
 204. Very truly yours,  
 205. J. Edgar Hoover  
 206. Director  
 207. Enclosure  
 208. Very truly yours,  
 209. J. Edgar Hoover  
 210. Director  
 211. Enclosure  
 212. Very truly yours,  
 213. J. Edgar Hoover  
 214. Director  
 215. Enclosure  
 216. Very truly yours,  
 217. J. Edgar Hoover  
 218. Director  
 219. Enclosure  
 220. Very truly yours,  
 221. J. Edgar Hoover  
 222. Director  
 223. Enclosure  
 224. Very truly yours,  
 225. J. Edgar Hoover  
 226. Director  
 227. Enclosure  
 228. Very truly yours,  
 229. J. Edgar Hoover  
 230. Director  
 231. Enclosure  
 232. Very truly yours,  
 233. J. Edgar Hoover  
 234. Director  
 235. Enclosure  
 236. Very truly yours,  
 237. J. Edgar Hoover  
 238. Director  
 239. Enclosure  
 240.

6. NINA = 7890



**EMBANKMENT- ABUTMENT GUTTER**

3747801.50


UPSTREAM STA 10+20 to 11+00

STA 21+40 to 21+70

DOWNSTREAM STA 10+23 TO 10+10

STA 10+30 to 21+65

# AS BUT





## OUTLET CHANNEL

**NOVEL SECTION**

12345678910111213141516171819202122232425262728293031323334353637383940414243444546474849505152535455565758596061626364656667686970717273747576777879808182838485868788899091929394959697989910010110210310410510610710810911011111211311411511611711811912012112212312412512612712812913013113213313413513613713813914014114214314414514614714814915015115215315415515615715815916016116216316416516616716816917017117217317417517617717817918018118218318418518618718818919019119219319419519619719819920020120220320420520620720820921021121221321421521621721821922022122222322422522622722822923023123223323423523623723823924024124224324424524624724824925025125225325425525625725825926026126226326426526626726826927027127227327427527627727827928028128228328428528628728828929029129229329429529629729829930030130230330430530630730830931031131231331431531631731831932032132232332432532632732832933033133233333433533633733833934034134234334434534634734834935035135235335435535635735835936036136236336436536636736836937037137237337437537637737837938038138238338438538638738838939039139239339439539639739839940040140240340440540640740840941041141241341441541641741841942042142242342442542642742842943043143243343443543643743843944044144244344444544644744844945045145245345445545645745845946046146246346446546646746846947047147247347447547647747847948048148248348448548648748848949049149249349449549649749849950050150250350450550650750850951051151251351451551651751851952052152252352452552652752852953053153253353453553653753853954054154254354454554654754854955055155255355455555655755855956056156256356456556656756856957057157257357457557657757857958058158258358458558658758858959059159259359459559659759859960060160260360460560660760860961061161261361461561661761861962062162262362462562662762862963063163263363463563663763863964064164264364464564664764864965065165265365465565665765865966066166266366466566666766866967067167267367467567667767867968068168268368468568668768868969069169269369469569669769869970070170270370470570670770870971071171271371471571671771871972072172272372472572672772872973073173273373473573673773873974074174274374474574674774874975075175275375475575675775875976076176276376476576676776876977077177277377477577677777877978078178278378478578678778878979079179279379479579679779879980080180280380480580680780880981081181281381481581681781881982082182282382482582682782882983083183283383483583683783883984084184284384484584684784884985085185285385485585685785885986086186286386486586686786886987087187287387487587687787887988088188288388488588688788888989089189289389489589689789889990090190290390490590690790890991091191291391491591691791891992092192292392492592692792892993093193293393493593693793893994094194294394494594694794894995095195295395495595695795895996096196296396496596696796896997097197297397497597697797897998098198298398498598698798898999099199299399499599699799899910001001100210031004100510061007100810091010101110121013101410151016101710181019102010211022102310241025102610271028102910301031103210331034103510361037103810391040104110421043104410451046104710481049105010511052105310541055105610571058105910601061106210631064106510661067106810691070107110721073107410751076107710781079108010811082108310841085108610871088108910901091109210931094109510961097109810991100110111021103110411051106110711081109111011111112111311141115111611171118111911201121112211231124112511261127112811291130113111321133113411351136113711381139114011411142114311441145114611471148114911501151115211531154115511561157115811591160116111621163116411651166116711681169117011711172117311741175117611771178117911801181118211831184118511861187118811891190119111921193119411951196119711981199120012011202120312041205120612071208120912101211121212131214121512161217121812191220122112221223122412251226122712281229123012311232123312341235123612371238123912401241124212431244124512461247124812491250125112521253125412551256125712581259126012611262126312641265126612671268126912701271127212731274127512761277127812791280128112821283128412851286128712881289129012911292129312941295129612971298129913001

**U.S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE**

28



WAS 1/8" THICKNESS PRIOR TO COMPACTION  
2. ACCEPT ON STANDARD PROCTOR

# AS BUTT


WASHINGTON MOUNTAIN BROOK WATERSHED PROJECT  
WASHINGTON MOUNTAIN LAKE MULTIPLE-PURPOSE DAM  
OCTOBER MOUNTAIN STATE FOREST, MASSACHUSETTS

**FILL PLACEMENT**  
**U.S. DEPARTMENT OF AGRICULTURE**  
**SOIL CONSERVATION SERVICE**

### FILE PLACEMENT:

Account	Debit	Credit	Balance
1000		1000	1000
1010		1010	1010
1020		1020	1020
1030		1030	1030
1040		1040	1040
1050		1050	1050
1060		1060	1060
1070		1070	1070
1080		1080	1080
1090		1090	1090
1100		1100	1100
1110		1110	1110
1120		1120	1120
1130		1130	1130
1140		1140	1140
1150		1150	1150
1160		1160	1160
1170		1170	1170
1180		1180	1180
1190		1190	1190
1200		1200	1200
1210		1210	1210
1220		1220	1220
1230		1230	1230
1240		1240	1240
1250		1250	1250
1260		1260	1260
1270		1270	1270
1280		1280	1280
1290		1290	1290
1300		1300	1300
1310		1310	1310
1320		1320	1320
1330		1330	1330
1340		1340	1340
1350		1350	1350
1360		1360	1360
1370		1370	1370
1380		1380	1380
1390		1390	1390
1400		1400	1400
1410		1410	1410
1420		1420	1420
1430		1430	1430
1440		1440	1440
1450		1450	1450
1460		1460	1460
1470		1470	1470
1480		1480	1480
1490		1490	1490
1500		1500	1500
1510		1510	1510
1520		1520	1520
1530		1530	1530
1540		1540	1540
1550		1550	1550
1560		1560	1560
1570		1570	1570
1580		1580	1580
1590		1590	1590
1600		1600	1600
1610		1610	1610
1620		1620	1620
1630		1630	1630
1640		1640	1640
1650		1650	1650
1660		1660	1660
1670		1670	1670
1680		1680	1680
1690		1690	1690
1700		1700	1700
1710		1710	1710
1720		1720	1720
1730		1730	1730
1740		1740	1740
1750		1750	1750
1760		1760	1760
1770		1770	1770
1780		1780	1780
1790		1790	1790
1800		1800	1800
1810		1810	1810
1820		1820	1820
1830		1830	1830
1840		1840	1840
1850		1850	1850
1860		1860	1860
1870		1870	1870
1880		1880	1880
1890		1890	1890
1900		1900	1900
1910		1910	1910
1920		1920	1920
1930		1930	1930
1940		1940	1940
1950		1950	1950
1960			





### 20" PIPE DATA

20" REINFORCED CONCRETE WATER PIPE	80
21' 40' SECTIONS	18' 0"
21' 40' SECTIONS	50.0
21' 40' SECTIONS	TOTAL: 64.0

### NOTE FOR THE PIPE SUPPLIER

CASING 31.5" BELL RING JOINT WITH CONCRETE ON ONE (4) PIPE SECTION

### PLAN



JOINT	INLET	INVERT
INLET	0	1771.00
J A	4	1770.97
J B	20	1770.88
J C	40	1770.70
J D	60	1770.50
OUTLET	64	1770.30

COLLAR	DISTANCE FROM INVERT	ANTI-SLEEP COLLARS
I	10.33	1762.47
II	30.33	1762.34
III	50.33	1762.08
IV	70.33	1761.70

JOINT	DISTANCE FROM INVERT	30" PIPE JOINTS
C 33	1762.50	
D 33	1762.44	
E 33	1762.34	
F 33	1762.08	
G 33	1761.92	
H 33	1761.87	
I 33	1761.80	
J 33	1761.70	
K 33	1761.50	
L 33	1761.30	
M 33	1761.00	
N 33	1760.80	
O 33	1760.50	
P 33	1760.30	
Q 33	1760.00	
R 33	1759.80	
S 33	1759.50	
T 33	1759.30	
U 33	1759.00	
V 33	1758.80	
W 33	1758.50	
X 33	1758.30	
Y 33	1758.00	
Z 33	1757.80	
AA 33	1757.50	
AB 33	1757.30	
AC 33	1757.00	
AD 33	1756.80	
AE 33	1756.50	
AF 33	1756.30	
AG 33	1756.00	
AH 33	1755.80	
AI 33	1755.50	
AJ 33	1755.30	
AK 33	1755.00	
AL 33	1754.80	
AM 33	1754.50	
AN 33	1754.30	
AO 33	1754.00	
AP 33	1753.80	
AQ 33	1753.50	
AR 33	1753.30	
AS 33	1753.00	
AT 33	1752.80	
AU 33	1752.50	
AV 33	1752.30	
AW 33	1752.00	
AX 33	1751.80	
AY 33	1751.50	
AZ 33	1751.30	
BA 33	1751.00	
BB 33	1750.80	
BC 33	1750.50	
BD 33	1750.30	
BE 33	1750.00	
BF 33	1749.80	
BG 33	1749.50	
BH 33	1749.30	
BI 33	1749.00	
BJ 33	1748.80	
BK 33	1748.50	
BL 33	1748.30	
BM 33	1748.00	
BN 33	1747.80	
BO 33	1747.50	
BP 33	1747.30	
BQ 33	1747.00	
BR 33	1746.80	
BS 33	1746.50	
BT 33	1746.30	
BU 33	1746.00	
BV 33	1745.80	
BW 33	1745.50	
BX 33	1745.30	
BY 33	1745.00	
BZ 33	1744.80	
CA 33	1744.50	
CB 33	1744.30	
CC 33	1744.00	
CD 33	1743.80	
CE 33	1743.50	
CF 33	1743.30	
CG 33	1743.00	
CH 33	1742.80	
CI 33	1742.50	
CJ 33	1742.30	
CK 33	1742.00	
CL 33	1741.80	
CM 33	1741.50	
CN 33	1741.30	
CO 33	1741.00	
CP 33	1740.80	
CQ 33	1740.50	
CR 33	1740.30	
CS 33	1740.00	
CT 33	1739.80	
CU 33	1739.50	
CV 33	1739.30	
CW 33	1739.00	
CX 33	1738.80	
CY 33	1738.50	
CZ 33	1738.30	
DA 33	1738.00	
DB 33	1737.80	
DC 33	1737.50	
DD 33	1737.30	
DE 33	1737.00	
DF 33	1736.80	
DG 33	1736.50	
DH 33	1736.30	
DI 33	1736.00	
DJ 33	1735.80	
DK 33	1735.50	
DL 33	1735.30	
DM 33	1735.00	
DN 33	1734.80	
DO 33	1734.50	
DP 33	1734.30	
DQ 33	1734.00	
DR 33	1733.80	
DS 33	1733.50	
DT 33	1733.30	
DU 33	1733.00	
DV 33	1732.80	
DW 33	1732.50	
DX 33	1732.30	
DY 33	1732.00	
DZ 33	1731.80	
EA 33	1731.50	
EB 33	1731.30	
EC 33	1731.00	
ED 33	1730.80	
EE 33	1730.50	
EF 33	1730.30	
EG 33	1730.00	
EH 33	1729.80	
EI 33	1729.50	
EJ 33	1729.30	
EK 33	1729.00	
EL 33	1728.80	
EM 33	1728.50	
EN 33	1728.30	
EO 33	1728.00	
EP 33	1727.80	
EQ 33	1727.50	
ER 33	1727.30	
ES 33	1727.00	
ET 33	1726.80	
EU 33	1726.50	
EV 33	1726.30	
EW 33	1726.00	
EX 33	1725.80	
EY 33	1725.50	
EZ 33	1725.30	
FA 33	1725.00	
FB 33	1724.80	
FC 33	1724.50	
FD 33	1724.30	
FE 33	1724.00	
FF 33	1723.80	
FG 33	1723.50	
FH 33	1723.30	
FI 33	1723.00	
FJ 33	1722.80	
FK 33	1722.50	
FL 33	1722.30	
FM 33	1722.00	
FN 33	1721.80	
FO 33	1721.50	
FP 33	1721.30	
FQ 33	1721.00	
FR 33	1720.80	
FS 33	1720.50	
FT 33	1720.30	
FU 33	1720.00	
FV 33	1719.80	
FW 33	1719.50	
FX 33	1719.30	
FY 33	1719.00	
FZ 33	1718.80	
GA 33	1718.50	
GB 33	1718.30	
GC 33	1718.00	
GD 33	1717.80	
GE 33	1717.50	
GF 33	1717.30	
GG 33	1717.00	
GH 33	1716.80	
GI 33	1716.50	
GJ 33	1716.30	
GK 33	1716.00	
GL 33	1715.80	
GM 33	1715.50	
GN 33	1715.30	
GO 33	1715.00	
GP 33	1714.80	
GQ 33	1714.50	
GR 33	1714.30	
GS 33	1714.00	
GT 33	1713.80	
GU 33	1713.50	
GV 33	1713.30	
GW 33	1713.00	
GX 33	1712.80	
GY 33	1712.50	
GZ 33	1712.30	
HA 33	1712.00	
HB 33	1711.80	
HC 33	1711.50	
HD 33	1711.30	
HE 33	1711.00	
HF 33	1710.80	
HG 33	1710.50	
HH 33	1710.30	
HI 33	1710.00	
HJ 33	1709.80	
HK 33	1709.50	
HL 33	1709.30	
HM 33	1709.00	
HN 33	1708.80	
HO 33	1708.50	
HP 33	1708.30	
HQ 33	1708.00	
HR 33	1707.80	
HS 33	1707.50	
HT 33	1707.30	
HU 33	1707.00	
HV 33	1706.80	
HW 33	1706.50	
HX 33	1706.30	
HY 33	1706.00	
HZ 33	1705.80	
IA 33	1705.50	
IB 33	1705.30	
IC 33	1705.00	
ID 33	1704.80	
IE 33	1704.50	
IF 33	1704.30	
IG 33	1704.00	
IH 33	1703.80	
II 33	1703.50	
IJ 33	1703.30	
IK 33	1703.00	
IL 33	1702.80	
IM 33	1702.50	
IN 33	1702.30	
IO 33	1702.00	
IP 33	1701.80	
IQ 33	1701.50	
IR 33	1701.30	
IS 33	1701.00	
IT 33	1700.80	
IU 33	1700.50	
IV 33	1700.30	
IW 33	1700.00	
IX 33	1699.80	
IY 33	1699.50	
IZ 33	1699.30	
JA 33	1699.00	
JB 33	1698.80	
JC 33	1698.50	
JD 33	1698.30	
JE 33	1698.00	
JF 33	1697.80	
JG 33	1697.50	
JH 33	1697.30	
JI 33	1697.00	
II 33	1696.80	
II 33	1696.50	
IJ 33	1696.30	
IK 33	1696.00	
IL 33	1695.80	
IM 33	1695.50	
IN 33	1695.30	
IO 33	1695.00	
IP 33	1694.80	
IQ 33	1694.50	
IR 33	1694.30	
IS 33	1694.00	
IT 33	1693.80	
IU 33	1693.50	
IV 33	1693.30	
IW 33	1693.00	
IX 33	1692.80	
IY 33	1692.50	
IZ 33	1692.30	
KA 33	1692.00	
KB 33	1691.80	
KC 33	1691.50	
KD 33	1691.30	
KE 33	1691.00	
KF 33	1690.80	
KG 33	1690.50	
KH 33	1690.30	
KI 33	1690.00	
KJ 33	1689.80	
KK 33	1689.50	
KL 33	1689.30	
KM 33	1689.00	
KN 33	1688.80	
KO 33	1688.50	
KP 33	1688.30	
KQ 33	1688.00	
KR 33	1687.80	
KS 33	1687.50	
KT 33	1687.30	
KU 33	1687.00	
KV 33	1686.80	
KW 33	1686.50	
KX 33	1686.30	
KY 33	1686.00	
KZ 33	1685.80	
LA 33	1685.50	
LB 33	1685.30	
LC 33	1685.00	
LD 33	1684.80	
LE 33	1684.50	
LF 33	1684.30	
LG 33	1684.00	
LH 33	1683.80	
LI 33	1683.50	
LJ 33	1683.30	
LK 33	1683.00	
LL 33	1682.80	
LM 33	1682.50	
LN 33	1682.30	
LO 33	1682.00	
LP 33	1681.80	
LQ 33	1681.50	
LR 33	1681.30	
LS 33	1681.00	
LT 33	1680.80	
LU 33	1680.50	
LV 33	1680.30	
LW 33	1680.00	
LX 33	1679.80	
LY 33	1679.50	
LZ 33	1679.30	
MA 33	1679.00	
MB 33	1678.80	
MC 33	1678.50	
MD 33	1678.30	
ME 33	1678.00	
MF 33	1677.80	
MG 33	1677.50	
MH 33	1677.30	
MI 33	1677.00	
MI 33	1676.80	
MJ 33	1676.50	
MK 33	1676.30	
ML 33	1676.00	
MM 33	1675.80	
MN 33	1675.50	
MO 33	1675.30	
MP 33	1675.00	
MQ 33	1674.80	
MR 33	1674.50	
MS 33	1674.30	
MT 33	1674.00	
MU 33	1673.80	
MV 33	1673.50	
MW 33	1673.30	
MX 33	1673.00	






Photo 11 - View of foundation drain outlet on left wall of impact basin looking down from east wall. Note silt from pipe held in hand of engineer.




Photo 12 - View of foundation drain 36 ft. left of impact basin looking northerly from downstream of dam. Note gravel and silt plugs outlet opening.



Photo 9 - View of principal spillway conduit outlet at impact basin looking north from basin. Note damaged concrete and exposed reinforcing bars.



Photo 10 - View of foundation drain outlet on right wall of impact basin looking west. Note damage AC pipe and plastic pipe insert.





Photo 7 - View of  
inside downstream  
flow conduit looking  
southerly. Note  
debris in conduit.




Photo 8 - View on riser  
crest looking northerly  
from upstream embankment.  
Note nuts missing from  
operator base and  
damage to concrete by  
vandals.



Photo 4 - Overview of approach to emergency spillway looking northerly from crest of spillway.



Photo 5 - Overview of discharge channel of emergency spillway looking southerly from crest of spillway.




Photo 6 - View of pond drain inlet and downstream flow conduit looking south.






Photo 1 - Overview  
of dam looking westerly  
from left abutment.  
Note roadway on crest.





Photo 2 - Overview of  
impoundment area and  
principal spillway  
looking northerly from  
dam crest.



Photo 3 - Overview of  
right abutment and  
emergency spillway look-  
ing westerly from dam  
crest. Note the wheel  
ruts on right slope of  
spillway left center  
of photo.



➤ OVERVIEW (AERIAL)

➤ APPENDIX C

TIGHE & BOND / SCI CONSULTING ENGINEERS EASTHAMPTON, MASS.		U.S.ARMY ENGINEER DIV. NEW ENGLAND CORPS OF ENGINEERS WALTHAM, MASS.	
NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS			
LOCATION AND ORIENTATION OF PHOTOS			
WASHINGTON MOUNTAIN LAKE DAM (MA 318) BERKSHIRE COUNTYMASSACHUSETTS			
			SCALE: NONE
			DATE: DECEMBER 1979

APPENDIX C  
PHOTOGRAPHS

**CONSTRUCTION NOTES**

1. THE 12" ASBESTOS CEMENT WATER PIPE SHALL BE NON-PRESSURE TO ALLOW FOR FUTURE EXPANSION TO ORIGINAL SPEC SIZE

2" ASBESTOS CEMENT WATER PIPE

SAND BLANKET

EXISTING 20" RE-REINFORCED CONCRETE WATER PIPE

**SECTION A-A**

1" ZONE 1 FILL

3 LAYERS OF HEAVY SMOOTH SURFACE ASPHALT TREATED WITH ROOFING FELT 10 LBS PER SQ

12" ASBESTOS CEMENT WATER PIPE

EXISTING 20" RE-REINFORCED CONCRETE WATER PIPE

**UPSTREAM ELEVATION (POND DRAIN INLET)**

**PROFILE OF 12" ASBESTOS CEMENT PIPE INSTALLATION**

SCALE 1" = 10'


METAL WEIR BILL OF MATERIALS			
ITEM	SIZE	LENGTH	QUANTITY
A	3" x 2" x 1/4"	-	2
B	3" x 2" x 1/4"	3'-3"	4
C	3" x 2" x 1/4"	2'-6"	2
EXPAN BOLTS	1/2" DIA	-	20
WELDS B WASH	-	-	-

**CONSTRUCTION NOTES (METAL WEIR)**

1. ANGLE BARS SHALL BE WELDED TO METAL WEIR AS SHOWN IN METAL WEIR DETAILS
2. METAL WEIR SHALL BE SECURED TO RISER WITH EXPANSION BOLTS THROUGH THE ANGLE BARS. THE EXPANSION BOLTS SHALL BE EVENLY SPACED APPROXIMATELY 12" ON CENTER
3. ALL CONTACT POINTS BETWEEN METAL AND CONCRETE SHALL BE SEALED WITH MASTIC TO FORM A WATERTIGHT SEAL

PERMANENT POOL ELEV 1786.0

SEE DETAIL "B"



**PLAN OF METAL WEIR**

**'AS BUILT'**

COMPLETION DATE: 5-27-70

CONTRACTOR: M.H.C. Co., Inc.

WASHINGTON MOUNTAIN BROOK WATERSHED PROJECT  
WASHINGTON MOUNTAIN BROOK WATERSHED DAM  
OCTOBER MOUNTAIN STATE FOREST, MASSACHUSETTS

**AS BUILT**

Prepared By: JAMES S. GILBERT  
Checked By: J. S. GILBERT  
Approved By: J. S. GILBERT

RISER MODIFICATION (BOTTOM RELEASE)  
U. S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

Project No.	100-100-100
Sheet No.	100-100-100
Date	5-27-70
Scale	1" = 10'
Drawn By	J. S. GILBERT
Checked By	J. S. GILBERT
Approved By	J. S. GILBERT

[illegible]

WASHINGTON MOUNTAIN BROOK WATERSHED PROJECT  
WASHINGTON MOUNTAIN - 400 MILES FROM SEATTLE  
COTTONWOOD MOUNTAIN STATE FOREST MASSACHUSETTS

LOGS OF TEST HOLES


U.S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

44-361 P


[illegible]




[illegible]




DOWNSTREAM ELEVATION




### SECTION ON CENTERLINE




**PLAN**



SECTION THROUGH DRAIN &amp; FILTER



11-20-54



ISOMETRIC VIEW

511-7700

[illegible]

WASHINGTON MOUNTAIN BROOK WATERSHED PROJECT  
WASHINGTON MOUNTAIN LAKE MULTIPLE-USE DAM  
OCTOBER MOUNTAIN STATE FOREST, MASSACHUSETTS

IMPACT BASIN DETAILS

Page 10  
J A T-000710 4-72  
Subject: F O W DA 68-72

## STANDARD IMPACT BASIN

RESEARCH ASSISTANT	1,400	1,600	1,800
LABORATORY	1,200	1,400	1,600

CARL ROMDE

**Abstract**

654 Ridgeway Rd Lake Geneva, Ore


**RESERVOIR DRAIN TRASH RACK BILL OF MATERIALS**

Item	Size	Length	Quan.
1. A-36 C	2" x 2" x 1/4"	15'	2
2. Anchor Bolt	1/2" Dia	5'	4

**CONSTRUCTION DETAILS**

1. Material in reservoir drain trash rack shall conform to Spec 561 for structural steel.
2. Trash rack to be galvanized in accordance with Spec 562.

**BAR TYPES**



**RESERVOIR DRAIN STEEL SCHEDULE**

Bar	Quan.	Size	Length	Type	B	C	D	Yds	Lbs
1	5	4	5	2	2	2	3	1	17.6
2	4	4	5	2	2	2	3	1	17.6
3	2	4	5	2	2	2	3	1	17.6
4	2	4	5	2	2	2	3	1	17.6
5	2	4	5	2	2	2	3	1	17.6
6	2	4	5	2	2	2	3	1	17.6
7	2	4	5	2	2	2	3	1	17.6
8	2	4	5	2	2	2	3	1	17.6
9	2	4	5	2	2	2	3	1	17.6
10	2	4	5	2	2	2	3	1	17.6
11	2	4	5	2	2	2	3	1	17.6
12	2	4	5	2	2	2	3	1	17.6
13	2	4	5	2	2	2	3	1	17.6
14	2	4	5	2	2	2	3	1	17.6
15	2	4	5	2	2	2	3	1	17.6
16	2	4	5	2	2	2	3	1	17.6
17	2	4	5	2	2	2	3	1	17.6
18	2	4	5	2	2	2	3	1	17.6
19	2	4	5	2	2	2	3	1	17.6
20	2	4	5	2	2	2	3	1	17.6
21	2	4	5	2	2	2	3	1	17.6
22	2	4	5	2	2	2	3	1	17.6
23	2	4	5	2	2	2	3	1	17.6
24	2	4	5	2	2	2	3	1	17.6
25	2	4	5	2	2	2	3	1	17.6
26	2	4	5	2	2	2	3	1	17.6
27	2	4	5	2	2	2	3	1	17.6
28	2	4	5	2	2	2	3	1	17.6
29	2	4	5	2	2	2	3	1	17.6
30	2	4	5	2	2	2	3	1	17.6
31	2	4	5	2	2	2	3	1	17.6
32	2	4	5	2	2	2	3	1	17.6
33	2	4	5	2	2	2	3	1	17.6
34	2	4	5	2	2	2	3	1	17.6
35	2	4	5	2	2	2	3	1	17.6
36	2	4	5	2	2	2	3	1	17.6
37	2	4	5	2	2	2	3	1	17.6
38	2	4	5	2	2	2	3	1	17.6
39	2	4	5	2	2	2	3	1	17.6
40	2	4	5	2	2	2	3	1	17.6
41	2	4	5	2	2	2	3	1	17.6
42	2	4	5	2	2	2	3	1	17.6
43	2	4	5	2	2	2	3	1	17.6
44	2	4	5	2	2	2	3	1	17.6
45	2	4	5	2	2	2	3	1	17.6
46	2	4	5	2	2	2	3	1	17.6
47	2	4	5	2	2	2	3	1	17.6
48	2	4	5	2	2	2	3	1	17.6
49	2	4	5	2	2	2	3	1	17.6
50	2	4	5	2	2	2	3	1	17.6
51	2	4	5	2	2	2	3	1	17.6
52	2	4	5	2	2	2	3	1	17.6
53	2	4	5	2	2	2	3	1	17.6
54	2	4	5	2	2	2	3	1	17.6
55	2	4	5	2	2	2	3	1	17.6
56	2	4	5	2	2	2	3	1	17.6
57	2	4	5	2	2	2	3	1	17.6
58	2	4	5	2	2	2	3	1	17.6
59	2	4	5	2	2	2	3	1	17.6
60	2	4	5	2	2	2	3	1	17.6
61	2	4	5	2	2	2	3	1	17.6
62	2	4	5	2	2	2	3	1	17.6
63	2	4	5	2	2	2	3	1	17.6
64	2	4	5	2	2	2	3	1	17.6
65	2	4	5	2	2	2	3	1	17.6
66	2	4	5	2	2	2	3	1	17.6
67	2	4	5	2	2	2	3	1	17.6
68	2	4	5	2	2	2	3	1	17.6
69	2	4	5	2	2	2	3	1	17.6
70	2	4	5	2	2	2	3	1	17.6
71	2	4	5	2	2	2	3	1	17.6
72	2	4	5	2	2	2	3	1	17.6
73	2	4	5	2	2	2	3	1	17.6
74	2	4	5	2	2	2	3	1	17.6
75	2	4	5	2	2	2	3	1	17.6
76	2	4	5	2	2	2	3	1	17.6
77	2	4	5	2	2	2	3	1	17.6
78	2	4	5	2	2	2	3	1	17.6
79	2	4	5	2	2	2	3	1	17.6
80	2	4	5	2	2	2	3	1	17.6
81	2	4	5	2	2	2	3	1	17.6
82	2	4	5	2	2	2	3	1	17.6
83	2	4	5	2	2	2	3	1	17.6
84	2	4	5	2	2	2	3	1	17.6
85	2	4	5	2	2	2	3	1	17.6
86	2	4	5	2	2	2	3	1	17.6
87	2	4	5	2	2	2	3	1	17.6
88	2	4	5	2	2	2	3	1	17.6
89	2	4	5	2	2	2	3	1	17.6
90	2	4	5	2	2	2	3	1	17.6
91	2	4	5	2	2	2	3	1	17.6
92	2	4	5	2	2	2	3	1	17.6
93	2	4	5	2	2	2	3	1	17.6
94	2	4	5	2	2	2	3	1	17.6
95	2	4	5	2	2	2	3	1	17.6
96	2	4	5	2	2	2	3	1	17.6
97	2	4	5	2	2	2	3	1	17.6
98	2	4	5	2	2	2	3	1	17.6
99	2	4	5	2	2	2	3	1	17.6
100	2	4	5	2	2	2	3	1	17.6

**QUANTITIES (This Sheet Only)**



**STEEL**

4.80' 266.6' 28' LBS

**CONCRETE**

CLASS 4000 3.0 C. Yds Reinforce


**TRASH RACK**



**SECTION DD**

**SECTION BB**

3 Layers of heavy, smooth surface, asphalt treated roofing felt, 55 lbs per sq



**SECTION AA**

**SECTION CC**

**REINFORCED CONCRETE RESERVOIR DRAIN INLET**  
(CLASS 4000 CONC)

WASHINGTON MOUNTAIN BROOK WATERSHED PROJECT  
WASHINGTON MOUNTAIN LAKE MULTIPLE PURPOSE DAM  
OCTOBER MOUNTAIN STATE FOREST, MASSACHUSETTS

RESERVOIR DRAIN INLET DETAILS  
U.S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

DATE: 10/1/55  
BY: J. H. KELLEY  
CHECKED: J. H. KELLEY  
APPROVED: J. H. KELLEY  
MA-361-P

# STEEL SCHEDULE

See Notes on Page 4, Appendix


Size	Weight	Type	Notes
1/2"	1.10	1	24
3/4"	1.68	2	24
1"	2.41	3	24
1 1/4"	3.76	4	24
1 1/2"	4.99	5	24
2"	7.70	6	24
2 1/2"	12.00	7	24
3"	17.80	8	24
3 1/2"	24.70	9	24
4"	32.80	10	24
4 1/2"	42.00	11	24
5"	51.00	12	24
5 1/2"	61.00	13	24
6"	71.00	14	24
6 1/2"	82.00	15	24
7"	93.00	16	24
7 1/2"	105.00	17	24
8"	117.00	18	24
8 1/2"	130.00	19	24
9"	143.00	20	24
9 1/2"	157.00	21	24
10"	171.00	22	24
10 1/2"	186.00	23	24
11"	201.00	24	24
11 1/2"	217.00	25	24
12"	233.00	26	24
12 1/2"	250.00	27	24
13"	267.00	28	24
13 1/2"	285.00	29	24
14"	303.00	30	24
14 1/2"	322.00	31	24
15"	341.00	32	24
15 1/2"	361.00	33	24
16"	381.00	34	24
16 1/2"	402.00	35	24
17"	423.00	36	24
17 1/2"	445.00	37	24
18"	467.00	38	24
18 1/2"	490.00	39	24
19"	513.00	40	24
19 1/2"	537.00	41	24
20"	561.00	42	24
20 1/2"	586.00	43	24
21"	611.00	44	24
21 1/2"	637.00	45	24
22"	663.00	46	24
22 1/2"	690.00	47	24
23"	717.00	48	24
23 1/2"	745.00	49	24
24"	773.00	50	24

## QUANTITIES

For Steel Schedule Item	2.325
For Steel Schedule Item	9.4
For Steel Schedule Item	2.4
For Steel Schedule Item	8.72

GLASS 4000 CONCRETE

## BAR TYPES




## SUGGESTED SUPPORT BLOCKS

WASHINGTON MOUNTAIN BROOK WATERSHED PROJECT  
WASHINGTON MOUNTAIN LAKE MULTIPLE-USE PROJECT  
WASHINGTON MOUNTAIN STATE FOREST, WASHINGTON


U.S. DEPARTMENT OF AGRICULTURE  
SOIL CONSERVATION SERVICE

PROJECT NO. 1-1000-115  
DATE 1-1-68  
SHEET 2 OF 36


## DETAIL OF ANTI-SEEP COLLAR YOKE




## DETAIL OF ANTI-SEEP COLLAR




## DETAIL OF BEDDING




## SECTION D-D




## SECTION C-C



## DETAIL OF PIPE JOINT



## DETAIL OF SPIGOT WALL FITTING




## STRENGTH REQUIREMENTS

Item	Requirement
1. Minimum Strength	10,000 psi
2. Maximum Strength	15,000 psi
3. Tensile Strength	10,000 psi
4. Compressive Strength	15,000 psi

## JOINT REQUIREMENTS

Item	Requirement
1. Minimum Strength	10,000 psi
2. Maximum Strength	15,000 psi
3. Tensile Strength	10,000 psi
4. Compressive Strength	15,000 psi

## DETAIL B



STANDARD CONDUIT DETAILS

REINFORCED CONCRETE PRESSURE PIPE

STANDARD SPEC NO. 5030-BE

DATE 2-76

SHEET 1 OF 1




Photo 13 - View of impact  
basin structure looking  
northeasterly from down-  
stream.

APPENDIX D

APPENDIX D

OUTLINE OF DRAINAGE AREA AND  
HYDRAULIC COMPUTATIONS

COMPUTATIONS

Page No.

Drainage Area Map

D-1

Size Classification, Hazard Potential and  
Test Flood Determination

D-2

Flood Routing, RMP

D-4

Dam Failure Analysis

D-8





Hydrologic/Hydraulic Computations  
December 3, 1979 Checked by Moe 1025

Washington Mountain Lake Dam

Drainage Area = 832 Acres = 1.3 Square Miles

Water Surface = 224 Acres

Size Classification

Height of Dam = 44 Feet (Intermediate)

Storage (at spillway crest) = 3910 Acre-Feet (Intermediate)  
∴ Use Intermediate

Hazard Potential = High


Prob. Flood = PMF

Drainage Area

Basin has rolling hills towards the lake. The lake is located in the upper portion of the basin and the hills drain into the lake by way of multiple streams.

∴ Use rolling curve to determine PMF

PMF  $Q = (2300 \text{ cfs/sq mi}) (1.3 \text{ S.M.}) = 2990 \text{ CFS}$   
say 3000 CFS



WASHINGTON RIVER VALLEY  
WILDLIFE MANAGEMENT AREA

WOOD  
RIVER

O X

Lenox Dale  
(Nagart Sta.)

GRAND  
WILSON HILL RD.

TRAIL

STREET  
EAST

October  
Mountain  
1948'

Halfway  
Pond

Felton  
Lake

Washington  
Mountain  
Lake

Washington  
Mt. Lake  
Dan →

W

Cem.

OCTOBER

COUNTY

STATE

WASHINGTON MTN  
Washington

Upper  
Res  
1600

Cudding  
Lower  
Reservoir

Commons

Brook

D-3

Hydrology/Engineering Computer Applications  
December 3, 1992 Computation Checked By: Moe 2051

### Spillway and Conduit Plotting

The principal spillway has a weir length of 30.8' and is at elevation 1798.0

Set orifices are downstream of the weir in the river structure and are 1' X 1.25'. Two on each side of the river

High stage weirs exist at the top of the river. Two exist and

are 7.5' in length. The elevation of the weir is 1801.0  
A 30' Conduit carries the water from the river under the dam and this conduit limits the capacity of the spillway.  
The dam is provided with

an emergency spillway which is 50' wide and has side slopes sloping at 2 horiz. to 1 vert. The approach channel slopes up to the crest at 2% and the discharge channel slopes away from the crest at 4%. The ES spillway elevation is 1801.0

The information used to establish the elevations of Washington Nat Lake Dam was obtained from Record Plans and Design Data provided by the SCS.

There exists a 20" ID conduit for the panel dam. It is assumed that the dam will be closed for this analysis.

December-3, 1977

Computations

Checked By: Moe

30417

The following spillway and conduit rating information was taken from the hydraulic section of the Design Report for the W.M. Lake Site, prepared on the SCS. The following information is only a portion of the Stage - Discharge Data found on pg 13 of the hydraulic section.

## Stage - Discharge

Elevation	Q (CFS)
1798.1	3.0
.2	8.6
.3	15.3
.4	23.9
.5	33.4
.6	43.9
.7	49.4
.8	49.9
.9	50.0
1799.0	51.1
.2	52.3
.4	53.3
.6	54.5
.8	55.4
1800.0	56.4
.5	59.0
1801.0	61.5
.2	66.6
.4	75.0
.6	112.5
.8	167.1
1807.0	210.5
.5	235.1
1808.0	466.0
.5	626.9
1809.0	787.8

D-5

Design of a long-term storage reservoir  
for the Sugar Creek Watershed, Mo. 50%

### Reservoir Routing

Surcharge elevation to pass 3000 cfs

is 1804.5

$$\begin{array}{r} \text{Surcharge Volume} = 1804.5 \\ - 1782.8 \\ \hline 6.5 \text{ ft} \end{array}$$

From SCS Surface Area - Elevation curve  
we had a design volume of  
Surf. Area  $A = 263$  Acres

Surface Area at proposed spillway  
from same source  $A = 224$  Acres

$$\begin{aligned} \text{Volume of surcharge} &= \left( \frac{263 + 224}{2} \right) (6.5) \\ &= 1582.8 \text{ AF} \end{aligned}$$

$$Q = 1380 = 832 \text{ A}$$

$$\text{Depth} = \frac{1582.8 \text{ AF}}{832 \text{ A}} = 1.90 \text{ ft} = 22.8"$$

$22.8" > 18"$  Therefore the  
storage exceeds the runoff volume.  
The reservoir storage and spillway  
are adequate.

Trinity, 1911-1912 ...

Determining Reservoir Storage  
 Use Form D-11 from 1911  
 National Engineering Handbook entitled  
 Section 4 - Hydrology

Drain. Re-vel. - 4555 <sup>to</sup> 3225 AF  
 1350  
 Inflow Peak - 1320 AF  
 Outflow - < 788 CFS  
 Inflow Peak - 2000 CFS

For 1911/12 ...  
 ...  
 ...

IN (AF)	STOR. (CF)	OUTFLOW (CFS)
3225	1772.0	1804.45
3425	1783.5	1804.40
3525	1779.0	1804.35
3625	1769.5	1804.30
3725	1800.1	1804.25
3825	1800.5	1804.20
3925	1799.2	1804.15
4025	1800.5	1804.10
4125	1800.5	1804.05
4225	1800.5	1804.00

D-7A

... ..




FIGURE 17.11

D-73

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100	101	102	103	104	105	106	107	108	109	110	111	112	113	114	115	116	117	118	119	120	121	122	123	124	125	126	127	128	129	130	131	132	133	134	135	136	137	138	139	140	141	142	143	144	145	146	147	148	149	150	151	152	153	154	155	156	157	158	159	160	161	162	163	164	165	166	167	168	169	170	171	172	173	174	175	176	177	178	179	180	181	182	183	184	185	186	187	188	189	190	191	192	193	194	195	196	197	198	199	200	201	202	203	204	205	206	207	208	209	210	211	212	213	214	215	216	217	218	219	220	221	222	223	224	225	226	227	228	229	230	231	232	233	234	235	236	237	238	239	240	241	242	243	244	245	246	247	248	249	250	251	252	253	254	255	256	257	258	259	260	261	262	263	264	265	266	267	268	269	270	271	272	273	274	275	276	277	278	279	280	281	282	283	284	285	286	287	288	289	290	291	292	293	294	295	296	297	298	299	300	301	302	303	304	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321	322	323	324	325	326	327	328	329	330	331	332	333	334	335	336	337	338	339	340	341	342	343	344	345	346	347	348	349	350	351	352	353	354	355	356	357	358	359	360	361	362	363	364	365	366	367	368	369	370	371	372	373	374	375	376	377	378	379	380	381	382	383	384	385	386	387	388	389	390	391	392	393	394	395	396	397	398	399	400	401	402	403	404	405	406	407	408	409	410	411	412	413	414	415	416	417	418	419	420	421	422	423	424	425	426	427	428	429	430	431	432	433	434	435	436	437	438	439	440	441	442	443	444	445	446	447	448	449	450	451	452	453	454	455	456	457	458	459	460	461	462	463	464	465	466	467	468	469	470	471	472	473	474	475	476	477	478	479	480	481	482	483	484	485	486	487	488	489	490	491	492	493	494	495	496	497	498	499	500	501	502	503	504	505	506	507	508	509	510	511	512	513	514	515	516	517	518	519	520	521	522	523	524
--	---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----

Don Tapscott Analysis

$C_0 = \frac{1}{\sqrt{\pi}} \int_{-\infty}^{\infty} f(x) dx$

1.  $\frac{1}{2} \times \frac{1}{2} = \frac{1}{4}$   
 2.  $\frac{1}{2} \times \frac{1}{2} = \frac{1}{4}$

Yo - Total Amount From 1st  
2nd to 3rd An Failure

Not a bad idea to do some  
of these before because  
the more you do the more  
you know PNF. There are  
plenty of exercises.

$\frac{1}{\sqrt{2}} \begin{pmatrix} 1 & i \\ 0 & 1 \end{pmatrix}$

[illegible]

Return To Bridge on  
south side of Pol. Pass - S -  
about 1000 ft.


130000

D-8



Survey of Highway - 100 ft. Moe 7

Stationing 0+00 to 1+00



$$A = 0.8$$

$$B = 0.4987$$

$$C = \sqrt{10^2 + 10^2} = 14.14$$

$$20.037$$

$$S = 0.05$$

12,000 ft

Handwritten notes and calculations, mostly illegible due to fading and bleed-through. Some visible words include "Stationing", "100 ft", "Moe", "7", "0+00", "1+00", "10", "14.14", "45°", "A = 0.8", "B = 0.4987", "C = 14.14", "20.037", "S = 0.05", "12,000 ft".

0 2000 4000 6000

Q 2000

points for curve on

$$Q = \frac{1.483 A R^2 S^{1/2}}{n} \quad n = 0.03$$

$$Q = 1105 A R^2$$

$$Q = 1105 A R^2$$

$$Q = 1105 A R^2$$

$$Q = 1105 A R^2$$

D-9

U-15

October Mountain

Halfway Pond

Fulton Lake

Washington Mountain Lake

Dam Site

OCTOBER

Mountain

STAT

State

Washington

Upper

Point of Overflow

Cooling

Low

Washington Mt. Lake Dam Failure Downstream Impact Areas

Brook

D-10

AD-A154 496

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
WASHINGTON MOUNTAIN L. (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV DEC 79

2/2

UNCLASSIFIED


F/G 13/13

NL

END

FILMED

DTIC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

D-11

Design of 19575 / Computations / Checked by Moe 9-5- ✓

Q = 6,947.3 CFS (bridge capacity)

For design of bridge alone


with no headgate, the design

capacity is the design

capacity of 13,947.3 CFS

the design of the bridge

Second Downstream Crossing  
Bridge on Windward Side



n = 0.03

A = 1847.3 E


S = 0.03

WP = 59.1 FL

R = 3.12

Q = 3332.1 CFS (bridge capacity)

Testing of Power Output For  
1st Second Crossing



n = 0.03

A = 675.2

S = 0.03

WP = 10.5 FL

R = 0.57


D-12

Overheadgate Co. gate in creek, Mo. 100-

Recess length = 2000 F.

Char. Vel  $2000 \times (\frac{1}{2} \text{ sec} + \frac{1}{2} \text{ sec})$

15  
10  
5



Q CFS

negative pressure in the recess

$$Q = \frac{1.49 C (A) (h^{3/2})}{0.05} (0.05)^{1/2}$$

Try  $Y = 5$

$$Q = \frac{1.49 C (0.5 \times 25) (20.5)^{3/2}}{0.05} (0.05)^{1/2}$$

26,070 CFS

1.  $Y = 6'$

D-13

$$Q = 48 \times (0.5 \times 64) (4)^{3/2} (0.05)^{1/2}$$

97,815.5 CFS

Open Channel Hydraulics Computations Checked By Moe

Estimate Peak Outflow

$$For\ Q_{ps} = 6.5'$$

$$V = (2000) \left( \frac{1}{2} 90 (6.5)^2 + \frac{1}{2} 45 (6.5)^2 \right)$$

$$= 130\ AF$$

$$Q_{ps} (4711) = (53,611.4) \left( 1 - \frac{130}{4711} \right)$$

$$= 52,132\ CFS\ y = 6.25$$

$$V = (2000) (1758 + 900)$$

$$= 121\ AF$$

$$V_{ave} = \frac{130 + 121}{2} = 125.5$$

$$Q_{ps} = 53,611.4 \left( 1 - \frac{126}{4711} \right) =$$


$$Q_{ps} = 52,178\ CFS\ y = 6.25$$

Since the water level is 7.5 ft above the bridge deck, the water will not flow over the bridge deck. Since the flow depth is 7.5 ft, the water will not flow over the bridge deck. The water will flow under the bridge deck. The water will flow under the bridge deck.



Hydrology/Engineering Computed by J. L. Lander  
 Dec. 10, 1973 Computations checked by Moe 120 ft

The Third Down stream Crossing  
 On Washington Ave. Road Near  
 Mill St




A = 120 SF  $n = 0.03$   
 WP = 38 Ft  $S = 0.012$   
 R = 3.15

$$Q = \frac{1.486}{0.03} (120) (3.15)^{2/3} (0.012)^{1/2}$$

$$Q = 14.72 \text{ CFS}$$

The Fourth Crossing  
 On Mill St



A = 93.4 SF  $n = 0.03$   
 WP = 34.96 Ft  $S = 0.012$   
 R = 2.67


$$Q = 1015.5 \text{ CFS}$$

D-15

Designing for Competitions Checked By Moe 1302

Since the third and fourth  
crossings are single spans  
the same method for  
the total crossing

The Fifth Crossing  
R.R. Bridge Between Montrose  
River and Bull Mt




$$\begin{array}{r} 10.5 \\ 10.5 \\ 18.8 \\ \hline 39.8 \end{array}$$

$$\begin{array}{ll} N = 0.03 & A = 197.4 \text{ SF} \\ S = 0.012 & W.P. = 39.8 \\ & R = 4.96 \end{array}$$

$$Q = \frac{1.48}{0.55} (197.4) (4.96)^{3/2} (0.012)^{1/2}$$

$$Q = 3244 \text{ CFS}$$

Crossing the River Above  
Bridge




$$\begin{array}{l} \text{w/ Flood + V.} \\ \text{w.P. 40.0} \\ R = 4.96 \end{array}$$

D-16

$$A = 1.48 \times \frac{1}{0.55} \times 3244 \times 0.012^{1/2}$$

Discussed by [ ] Compared to [ ] checked by Moe 145



Comparison of Point on Curve  
To Point 3

$$Q = 5.65 A R^{2/3}$$

$$\text{Then } y = 10$$

$$Q = (5.65)(2000)(4.98)^{2/3}$$

$$= 33,120 \text{ CFD}$$

$$\text{Then } y = 12$$

$$Q = (5.65)(2000)(0.400 \times 12)^{2/3}$$

$$Q = 53,618 \text{ CFD}$$

June 19, 1977      Computation      checked by      Moe      1501

Edwards River 20.0

$$F_{ov} = C (52,178.05\%)$$

$$y = 11.75$$

$$L = 2000 \text{ FA}$$

$$V_1 = (2000 (20.1175)) = 126 \text{ AF}$$

$$V_2 = 126 \text{ AF}$$

$$Q_1 = (F_{ov}) (178.05\%) (1 - \frac{126}{4711})$$

$$= 50,762.4 - F_{ov} \quad y = 11.5\%$$

$$V_1 = 2000 (y \times 11.5) = 121 \text{ AF}$$

$$Q_2 = (52,173) (1 - \frac{123.5}{4711}) \quad V_{ave} = 123.5$$

$$Q_{ave} = \frac{50,762.4 + 52,173}{2} = 51,467.7 \quad 69,000 \text{ CFS}$$

$$y = 13.0 \text{ FA} \quad y =$$

$$8 \text{ min } 30 \text{ sec } \quad 926.0$$

71. C.F. 20.0

69,000 CFS

41.0

11.75

11.75

11.75

11.75

11.75

D-18

2. 1000 ft. ... Moer 1625

To ... To ...

69,000 = 2.6) ...

H = 876'

The ... the R-R ...

... 87654

... the ...

... the ...

G. 3244 CFN


... the ...

... the ...

along Mill St to the south

the ...

...



... the ...

... the ...

D-19

... 29" ...

1.  $50,810 \text{ cL} + 19,000 \text{ cL} = 69,810 \text{ cL}$   
 2.  $69,810 \text{ cL} \div 100 = 698.10 \text{ L}$   
 3.  $698.10 \text{ L} \div 1000 = 0.6981 \text{ m}^3$   
 4.  $0.6981 \text{ m}^3 \times 1000 = 698.10 \text{ L}$

Figure 1 is a line graph showing the relationship between the relative rate of polymerization ( $k_p/k_{p0}$ ) on the y-axis and the relative concentration of the initiator ( $C_i/C_{i0}$ ) on the x-axis. The x-axis ranges from 0 to 1.0 with major ticks every 0.2. The y-axis ranges from 1.0 to 1.5 with major ticks every 0.1. A single curve is plotted, starting at the point (0, 1.0) and increasing as  $C_i/C_{i0}$  increases. The curve is concave down, passing through approximately (0.2, 1.1), (0.4, 1.2), (0.6, 1.3), (0.8, 1.4), and ending at (1.0, 1.5).

[illegible]

D-5

October  
Mountain

Hollow  
Pool

Yellow  
Lake

Mountain  
Lake

OCTOBER

STAT

Upper  
Res

Cold  
Lake

Lower  
Pool

Brook

Chimney

Brook

D

9.0 38

6.0

17.0 17.0

10.0

17.0 17.0

7.0 7.0

17.0 17.0

17.0

17.0 17.0

17.0

17.0

17.0

D-2



APPENDIX E

INFORMATION AS CONTAINED IN  
THE NATIONAL INVENTORY OF DAMS

NOT AVAILABLE AT THIS TIME

**END**

**FILMED**

**7-85**

**DTIC**